

COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY MINERALS PROGRAM INSPECTION REPORT

PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:	MINE/PROSPECTING ID#:	MINERAL:	COUNTY:
Mineral Mountain Project	M-2014-045	Gold	Teller
INSPECTION TYPE:	INSPECTOR(S):	INSP. DATE:	INSP. TIME:
Surety-Related Inspection	Timothy A. Cazier	October 20, 2015	10:00
OPERATOR:	OPERATOR REPRESENTATIVE:	TYPE OF OPERATION:	
Mineral Mountain Gold, LLC	Lance Barker	110d - Designated Limited Impact	

REASON FOR INSPECTION:	BOND CALCULATION TYPE:	BOND AMOUNT:
Surety Related	None	\$28,350.00
DATE OF COMPLAINT:	POST INSP. CONTACTS:	JOINT INSP. AGENCY:
NA	U.S.BLM	None
WEATHER:	INSPECTOR'S SIGNATURE:	SIGNATURE DATE:
Cloudy	1 lm	October 23, 2015

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS <u>Y</u>	(FN) FINANCIAL WARRANTY N	(RD) ROADS <u>Y</u>
(HB) HYDROLOGIC BALANCE <u>N</u>	(BG) BACKFILL & GRADING <u>N</u>	(EX) EXPLOSIVES <u>N</u>
(PW) PROCESSING WASTE/TAILING Y	(SF) PROCESSING FACILITIES N	(TS) TOPSOIL <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- N	(FW) FISH & WILDLIFE N	(RV) REVEGETATION <u>Y</u>
(SM) SIGNS AND MARKERS <u>Y</u>	(SW) STORM WATER MGT PLAN N	(CI) COMPLETE INSP N
(ES) OVERBURDEN/DEV. WASTE <u>N</u>	(SC) EROSION/SEDIMENTATION N	(RS) RECL PLAN/COMP <u>Y</u>
(AT) ACID OR TOXIC MATERIALS N	(OD) OFF-SITE DAMAGE <u>Y</u>	(ST) STIPULATIONS \underline{Y}

 $Y = Inspected \ and \ found \ in \ compliance \ / \ N = \ Not \ inspected \ / \ NA = \ Not \ applicable \ to \ this \ operation \ / \ PB = Problem \ cited \ / \ PV = Possible \ violation \ cited \ PV = Possib$

OBSERVATIONS

This inspection was an acreage release inspection for the Mineral Mountain Project which overlaps the Minerex's Little Hope Mine reclamation permit (M-2004-064) and an adit exploration NOI (P-1986-036). The areas being released are small pockets of BLM managed land within the permit boundary. The Operator was represented by Lance Barker, who was present for the inspection. The Mineral Mountain Project is a 110d gold mine operated by Mineral Mountain Gold and located approximately 1.5 miles north of Cripple Creek in Teller Co. It is accessed from McKenney St.

Inspection:

New permit boundary makers were placed to mark the corners of BLM land. The west area included roughly 6,000 sqft of undisturbed forested BLM land (see **Photo 1**). The southeast corner included approximately 600 sqft of likely pre-law disturbed area that is supporting new conifer growth (see **Photo 2**). Each area's corners were marked with rebar stakes marked with BLM tags (see **Photos 3** and **4**).

Mr. Barker asked about putting a temporary roof over the ore storage area. We agree the use of supports bolted to the jersey barriers and a corrugated metal cover would be considered a temporary structure and have no impact on the financial warranty.

As no objections have been received, the Division will recommend approval of this acreage release. You will be notified under separate cover.

PHOTOGRAPHS



Photo 1. West BLM area to be released (Note rebar marker).

PHOTOGRAPHS (cont.)



Photo 2. Southeast corner BLM area to be released (Note: 3 rebar markers & conifer growth).



Photo 3. Typical west side area marker with BLM tag.

PHOTOGRAPHS (cont.)



Photo 4. Typical southeast corner area marker with BLM tag.

Inspection Contact Address

Lance Barker Mineral Mountain Gold, LLC P.O. Box 247 Cripple Creek, CO 80813

ec: Wally Erickson, DRMS

DRMS file

Stephanie Carter, BLM