



COLORADO

Division of Reclamation,
Mining and Safety


Department of Natural Resources

MINERALS PROGRAM INSPECTION REPORT

PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Corkle Pit	MINE/PROSPECTING ID#: M-1995-023	MINERAL: Sand and gravel	COUNTY: Jackson
INSPECTION TYPE: Monitoring	INSPECTOR(S): Peter S. Hays	INSP. DATE: June 24, 2016	INSP. TIME: 12:00
OPERATOR: Corkle Construction	OPERATOR REPRESENTATIVE: Harry Corkle	TYPE OF OPERATION: 110c - Construction Limited Impact	

REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: Partial Bond	BOND AMOUNT: \$20,900.00
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None
WEATHER: Clear	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: July 9, 2016

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>N</u>
(HB) HYDROLOGIC BALANCE----- <u>N</u>	(BG) BACKFILL & GRADING----- <u>N</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>Y</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(CI) COMPLETE INSP---- <u>Y</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>N</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	(ST) STIPULATIONS----- <u>N</u>

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

The Corkle Pit was inspected by Peter Hays with the Division of Reclamation, Mining and Safety (Division/DRMS) as part of the Division's monitoring inspection program. The inspection was conducted in conjunction with the surety release inspection for the adjoining Corkle Construction Pit #2. The site was previously inspected by the Division on September 17, 2015. Mr. Hughie Corkle and Mr. Harry Corkle with Corkle Construction were present during the inspection.

The site is permitted for 9.90 acres. The site was active during the inspection. The processing plant located in the southeast section of the site was operational. Product stockpiles were located on the pit floor. Mining excavation was progressing to the northeast next to the access road to the pit floor. Haul trucks were removing material from the site during the inspection.

The approved post mining land use for the site is rangeland. The Division holds a financial warranty in the amount of \$20,900.00, which appeared adequate to reclaim the current mining disturbance.

An entrance sign was posted and permit boundary markers were observed as required by Rule 3.1.12. No problems were noted during the inspection. Photographs taken during the inspection are attached.

Inspection Contact Address

Mr. Hughie Corkle
Corkle Construction
34612 Hwy. 14
Walden, CO 80480

Cc: Wally Erickson, DRMS

PHOTOGRAPHS



Looking SE at pit floor and processing plant



Looking NW at mining activity



Looking processing plant and stockpiles on pit floor