




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Beeman Pit #1	MINE/PROSPECTING ID#: M-2002-009	MINERAL: Sand and gravel and material for construc	COUNTY: Pueblo
INSPECTION TYPE: Monitoring	INSPECTOR(S): Tyler V. O'Donnell	INSP. DATE: March 15, 2016	INSP. TIME: 16:00
OPERATOR: Martin Marietta Materials, Inc.	OPERATOR REPRESENTATIVE: Julie Mikulas	TYPE OF OPERATION: 112c - Construction Regular Operation	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: Complete Bond	BOND AMOUNT: \$62,335.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
WEATHER: Windy	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: July 14, 2016	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>N</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>NA</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>Y</u>	(RV) REVEGETATION---- <u>Y</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(CI) COMPLETE INSP---- <u>Y</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>Y</u>	(RS) RECL PLAN/COMP-- <u>Y</u>
(AT) ACID OR TOXIC MATERIALS----- <u>Y</u>	(OD) OFF-SITE DAMAGE----- <u>Y</u>	(ST) STIPULATIONS----- <u>Y</u>

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This routine monitoring inspection was conducted by Tyler O'Donnell of the Division of Reclamation, Mining and Safety (Division). Martin Marietta Materials, Inc. (Operator), was represented by Julie Mikulas during the inspection.

The Beeman Pit #1 is located in Pueblo County approximately 14 miles southeast of Pueblo, Colorado. The Beeman Pit #1 is a 45-acre 112c Construction Materials Reclamation Permit. The permit was issued in May 2002. The primary commodity proposed to be mined at the site is sand and gravel. The approved post-mining land use is Rangeland. The mine site is surrounded by the following land uses, wildlife habitat, rangeland, mining, and rural residential.

During the inspection, the sky was clear and the ground was dry. No mining equipment was present at the time of the inspection. The mining operation has not started yet. The Site is still being used as rangeland. The Operator's representative stated that mining may begin when the company has a project in the nearby area. The current amount of financial warranty the Operator has on deposit with the State is \$ 62,335. Prior to mining, the Operator will need to notify the Division of the company's intent to mine the site. the Division will recalculate the required financial warranty using updated costs. The Division will provide the Operator an opportunity to comment on the required financial warranty. The required financial warranty maybe adjusted prior to the commencement of the mining operation.

Signs and Markers:

A mine I.D. sign was posted at the entrance to the site. The permit boundary was marked during the inspection.

Inspection Contact Address

Julie Mikulas
Martin Marietta Materials, Inc.
1800 N. Taft Hill Road
Fort Collins, CO 80521

cc: Wally Erickson, DRMS

PHOTOGRAPHS



