

MINERALS PROGRAM INSPECTION REPORT PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:		MINE/PROSPECTING ID#:	MINERAL:	COUNTY:	
Wright Pit		M-1986-140	Sand and gravel	Park	
INSPECTION TYPE:		INSPECTOR(S):	INSP. DATE:	INSP. TIME:	
Preoperation Inspection		Michael A. Cunningham	January 31, 2017	10:00	
OPERATOR:		OPERATOR REPRESENTATIVE:	TYPE OF OPERATION:		
Park County		Tammie Crawford	112c - Construction Regular Operation		
REASON FOR INSPECTION:		BOND CALCULATION TYPE:	BOND AMOUNT:		
Normal I&E Program		None	\$0.00		
DATE OF COMPLAINT:		POST INSP. CONTACTS:	JOINT INSP. AGENCY:		
NA		None	None		
WEATHER:	INSPECTOR'S SIGNATURE:		SIGNATURE DATE:		
Snowing	Ill C.L		April 4, 2017		

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS <u>N</u>	(FN) FINANCIAL WARRANTY NA	(RD) ROADS <u>N</u>
(HB) HYDROLOGIC BALANCE <u>N</u>	(BG) BACKFILL & GRADING <u>N</u>	(EX) EXPLOSIVES <u>NA</u>
(PW) PROCESSING WASTE/TAILING N	(SF) PROCESSING FACILITIES NA	(TS) TOPSOIL <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE <u>N</u>	(RV) REVEGETATION N
(SM) SIGNS AND MARKERS <u>Y</u>	(SP) STORM WATER MGT PLAN N	(CI) COMPLETE INSP $\underline{\mathbf{Y}}$
(ES) OVERBURDEN/DEV. WASTE N	(SC) EROSION/SEDIMENTATION N	(RS) RECL PLAN/COMP N
(AT) ACID OR TOXIC MATERIALS NA	(OD) OFF-SITE DAMAGE <u>Y</u>	(ST) STIPULATIONS <u>N</u>

 $Y = Inspected \ and \ found \ in \ compliance \ / \ N = \ Not \ inspected \ / \ NA = \ Not \ applicable \ to \ this \ operation \ / \ PB = \ Problem \ cited \ / \ PV = \ Possible \ violation \ cited \ PV = \ Possible \ PV = \ Possible \ PV = \ P$

PERMIT #: M-1986-140 INSPECTOR'S INITIALS: MAC INSPECTION DATE: January 31, 2017

OBSERVATIONS

The inspection was conducted by Michael Cunningham of the Division of Reclamation, Mining and Safety (Division). Tammie Crawford was present on behalf of Park County. The Wright Pit is located approximately 12 miles northeast of Fairplay, Colorado and about 3/4 mile north of Highway 285. The site is currently permitted for 9.64 acres and the post-mining land use is rangeland. The ground surface was covered with snow at the time of the inspection and visibility was low due to blowing snow.

Park County filed a Conversion Application on December 16, 2016 to increase the permit area to 160 acres. The inspection was conducted to verify that site conditions, as represented in the Conversion Application, were accurate. The Wright Pit was not operational at the time of the inspection and all processing equipment had been removed from the site. A single product stockpile was located at the west end of the pit. In addition, there were several product stockpiles which were located outside of the pit. These stockpiles are outside of the boundary of the 110c Reclamation Permit. The Operator may process/haul from the product stockpiles upon approval of the 112c Reclamation Permit.

The Division traversed the proposed permit boundary and found that it was adequately delineated by fence lines. In addition, all of the structures identified in the Conversion Application were accounted for and no new structures were observed. The public notice sign with information about the Conversion Application was posted at the site entrance.

This concluded the inspection.

PHOTOGRAPHS



1. View of pit floor, photo taken facing west.



2. Product stockpile within pit.



3. View of pit floor, photo taken facing north.

Inspection Contact Address

Tammie Crawford Park County P.O. Box 147 Fairplay, CO 80440

CC: Wally Erickson, DRMS