

## MINERALS PROGRAM INSPECTION REPORT PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:		MINE/PROSPECTING ID#:	MINERAL:	COUNTY:
La Florida Gravel Pit		M-1987-097	Sand and gravel	Conejos
INSPECTION TYPE:		INSPECTOR(S):	INSP. DATE:	INSP. TIME:
Monitoring		Dustin M. Czapla	May 15, 2017	18:30
OPERATOR:		OPERATOR REPRESENTATIVE:	TYPE OF OPERATION:	
Conejos County		None	112c - Construction Regular Operation	
				1
REASON FOR INSPECTION:		BOND CALCULATION TYPE:	BOND AMOUNT:	
Normal I&E Program		None	\$0.00	
DATE OF COMPLAINT:		POST INSP. CONTACTS:	JOINT INSP. AGENCY:	
NA		None	None	
WEATHER:	INSPECTOR'S SIGNATURE:		SIGNATURE DAT	E:
Clear	R		May 19, 2017	

## **GENERAL INSPECTION TOPICS**

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS <u>Y</u>	(FN) FINANCIAL WARRANTY N	(RD) ROADS <u>N</u>
(HB) HYDROLOGIC BALANCE <u>Y</u>	(BG) BACKFILL & GRADING <u>Y</u>	(EX) EXPLOSIVES N
(PW) PROCESSING WASTE/TAILING N	(SF) PROCESSING FACILITIES $\underline{N}$	(TS) TOPSOIL <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE $\underline{N}$	(RV) REVEGETATION <u>Y</u>
(SM) SIGNS AND MARKERS <u>Y</u>	(SP) STORM WATER MGT PLAN N	(CI) COMPLETE INSP $\underline{Y}$
(ES) OVERBURDEN/DEV. WASTE <u>N</u>	(SC) EROSION/SEDIMENTATION $\underline{Y}$	(RS) RECL PLAN/COMP Y
(AT) ACID OR TOXIC MATERIALS N	(OD) OFF-SITE DAMAGE <u>N</u>	(ST) STIPULATIONS <u>N</u>

 $Y = Inspected \ and \ found \ in \ compliance \ / \ N = Not \ inspected \ / \ NA = Not \ applicable \ to \ this \ operation \ / \ PB = Problem \ cited \ / \ PV = Possible \ violation \ cited \ A = Not \ applicable \ to \ this \ operation \ / \ PB = Problem \ cited \ / \ PV = Possible \ violation \ viola$ 

PERMIT #: M-1987-097 INSPECTOR'S INITIALS: DMC INSPECTION DATE: May 15, 2017

## **OBSERVATIONS**

This inspection was conducted as part of the Division of Reclamation, Mining and Safety's (Division) normal monitoring program. The operator was not present during the inspection. Photographs are included with this report in order to illustrate some of the conditions observed.

The La Florida Gravel Pit is located approximately 5.5 miles southeast of Antonito and accessed from CR 18. The site is a 112c operation that includes a total of forty permitted acres. The permit was converted to a 112c in May 2007. Pursuant to Rule 4.1.2 (2), a financial warranty is not required for this site.

Adequate mine identification signage was noted at the entrance to the site.

The affected area was marked by fencing that was clearly visible and adequate to delineate the affected area boundary.

At this time, there are approximately nineteen acres disturbed at this site. The pit is approximately 25 feet deep. Nearly all of the highwalls are reduced to 3H:1V slopes. Several materials stockpiles are located on the pit floor. There was no processing equipment or fuels stored at the site.

No problems or violations were noted during this inspection.

Responses to this inspection report should be directed to Dustin Czapla at the Division of Reclamation, Mining and Safety, Grand Junction Field Office, 101 South 3<sup>rd</sup> Street, Room 301, Grand Junction, Colorado 81501, phone number (970) 243-6299.

## **Inspection Contact Address**

Phil Esquibel Conejos County P.O. Box 157 Conejos, CO 81129











