

1313 Sherman Street, Room 215, Denver, CO 80203 P 303.866.3567 F 303.832.8106 http://mining.state.co.us

PERMIT INFORMATION

Permit Number: C-1996-084 Mine Name: Lorencito Canyon Mine Operator: New Elk Coal Company, LLC Operator Address: Mr. Louis Head 12250 Highway 12 Weston, CO 81091 **County:** Las Animas **Operation Type:** Surface **Permit Status:** Permanent Cessation **Ownership:** Private

Operator Representative Present:

Vince Massarotti

Operator Representative Signature: (Field Issuance Only)

INSPECTION INFORMATION

Inspection Start Date: June 8, 2017 Inspection Start Time: 09:00 Inspection End Date: June 9, 2017 Inspection End Time: 10:30			Inspection Type: Coal Complete Inspection Inspection Reason: Normal I&E Program Weather: Clear		
Joint Inspection Agency:		Joint Inspection Contacts:			
None					
Post Inspection Agency:		Post Inspection Contacts:			
None					
Inspector(s):	Inspecto	r's Sig	nature: Signature Date:		
Robert D. Zuber, P.E.	Phot	D.	24		
			6/20/2017		

Inspection Topic Summary

NA - Air Resource Protection	Y - Roads
R - Availability of Records	R - Reclamation Success
NA - Backfill & Grading	Y - Revegetation
R - Excess Spoil and Dev. Waste	NA - Subsidence
NA - Explosives	Y - Slides and Other Damage
Y - Fish & Wildlife	NA - Support Facilities On-site
R - Hydrologic Balance	Y - Signs and Markers
Y - Gen. Compliance With Mine Plan	Y - Support Facilities Not On-site
N - Other	Y - Special Categories Of Mining
NA - Processing Waste	Y - Topsoil

COMMENTS

A complete inspection was conducted by Rob Zuber of DRMS on June 8 (records check) and June 9, 2017. The weather was clear and warm. The ground was somewhat muddy from recent rains. Vince Massarotti of NECC was present for the on-the-ground portion of the inspection.

AVAILABILITY OF RECORDS

Records needed to be updated at time of inspection. This includes the Reclamation Cost Estimate that was updated with MT-04.

EXCESS SPOIL and DEVELOPMENT WASTE – Rule 4.09 Placement; Drainage Control; Surface Stabilization:

Fills 7, 8, and 9 were inspected. All were generally in good condition, but the following should be addressed. Rills on Fill 7 (as noted in past inspections) may require repair; this remains a judgement call, and NECC should balance the pros and cons of this work. The gully near the bottom of Fill 7 does require repair. Riprap work is needed in down drains for Fill 9.

HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

The following ponds were inspected: 5, 6, 7, 8, 9, and 9A. Several of them were discharging relatively clear water. Ponds 6, 7 and 9 were not discharging. Embankments were in good condition. It appears that primary spillways at Ponds 8 and 9A have small leaks that should be sealed as soon as practical, perhaps during the dry season in late summer 2017. Pond 5 appears to be in need of cleaning, as the sediment level is almost up to the lowest holes on the riser of the spillway.

Number of <u>Partial</u> Inspection this Fiscal Year: 9 Number of <u>Complete</u> Inspections this Fiscal Year: 4 Culvert C8 (above Fill 8) is clear of sediment, and the ditch below it is stable.

In the channel above Pond 6, check dams appear to be functioning, but more riprap should be added to the channel between the dams, at least in one spot (this was discussed with Vince Massarotti during the inspection).

RECLAMATION SUCCESS - Rule 4.15, Rule 3:

The hill above the pond cleaning dump area continues to have several rills that should be repaired. Vince Massarotti indicated that elk have displaced wattles on this hill, so he will use tree branches for erosion control in this area.

In the Pond 5 watershed, there is only a small area that is disturbed. This area is mostly stable.

Rills on the west side of "the knob" (large hill in center of site) require repair. Erosion near the shrub plot has been addressed.

On the hillside above Pond 6 (where Fill 6 was planned), work on the rills has been performed.

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

PHOTOGRAPHS



Sediment in Pond 5



Hill above area where pond cleanings are dumped



Fill 8







Erosion repairs near shrub plot



Channel above Pond 6

Area in need of riprap



Rills on Fill 7



Side channel, aka west down drain, at Fill 9 (need for more riprap)

Number of <u>Partial</u> Inspection this Fiscal Year: 9 Number of <u>Complete</u> Inspections this Fiscal Year: 4

AVAILABILITY OF RECORDS

PERMIT RECORDS		HYDROLOGIC RECORDS					
DRMS Permit	Expires	NPDES Permit	CO0048988				
	11/7/2017		(unsigned)				
Permit Application w/Revisions	yes	NPDES Records	Q3 2015				
	J U S		(terminated				
			monitoring)				
Findings Document	RN3, 3/21/13	Stormwater Management Plan	2007				
Insurance Certificate	Exp.	SPCC Plan	n/a				
	April 2018						
Bond Document	\$927,121.00	MSHA Pond Inspections	n/a				
Phased Bond Release	SL2,						
Documents/Findings	Findings 4/29/08	State Engineer's Pond Inspection	n/a				
Air Emission Permits	Terminated	Quarterly Pond Inspections	Q3 2016				
County Special Use Permits	SUP-01-020	Annual Hydrology Reports	Terminated				
UG Mining Landowner Notification	n/a	 Ground Water Monitoring 					
Subsidence Monitoring Reports	n/a	 Surface Water Monitoring 					
Subsidence Monitoring Data	n/a	 Spring & Seep Monitoring 					
Rill & Gully Survey	n/a	Mine Water Discharge					
		Monitoring					
Vegetation Monitoring Data		Mine Inflow Study					
Specific Variance Approvals	n/a	Water Consumption Records					
Annual Reclamation Reports	2015	-	201451, 201453-				
-		Well Permits	201476				
Midterm Review Documents	MT4 (findings						
	Jan. 2016)						
DRMS/OSM Inspection	Through						
Reports/Enforcement Actions	Feb. 2017	BLASTING RECORDS					
Transfers/Succession of Operator	Executed 2008	Blasting Publication	n/a				
Temporary Cessation Notification	n/a	Blasting Records (3 years)	n/a				
Reclamation Cost Estimate	RN3, \$916,169	ATFE Explosives Permit	n/a				
CERTIFICATIONS		Blasting Variances	n/a				
Pond Certifications	Yes, Exhibit 15	Pre-Blast Surveys	n/a				
Annual Certifications for Impoundments	n/a						
Fill Certifications for Excess Spoil	yes	ADDITIONAL RECORDS					
or Underground Development Waste		(specify)					
Quarterly Inspections	Q1 2017						
Compaction Testing							
Final Certification							
Coal Processing Waste Banks	n/a						
Haul Road Certifications	yes						
Access Road Certifications	yes						
	*						
COMMENTS: None at this time							

Number of <u>Partial</u> Inspection this Fiscal Year: 9 Number of <u>Complete</u> Inspections this Fiscal Year: 4