

1313 Sherman Street, Room 215, Denver, CO 80203 P 303.866.3567 F 303.832.8106 http://mining.state.co.us

PERMIT INFORMATION

Permit Number: C-1984-065 Mine Name: Coal Ridge No. 1 Mine Operator: C.B. Minerals Company, LLC Operator Address: Mr. James Stover 2352 N 7th St, Ste. B Grand Junction, CO 81501 County: Garfield Operation Type: Underground Permit Status: Inactive Ownership: Private

Operator Representative Present:

None

Operator Representative Signature: (Field Issuance Only)

INSPECTION INFORMATION

Inspection Start Date: July 21, 2 Inspection Start Time: 09:00 Inspection End Date: July 21, 20 Inspection End Time: 12:00			Inspection Type: Coal C Inspection Reason: Norr Weather: Cloudy	· ·
Joint Inspection Agency:		Joint Inspection Contacts:		
None				
Post Inspection Agency:		Post Inspection Contacts:		
None				
Inspector(s):	Inspecto			Signature Date:
Brock F. Bowles	Brak	Sa	ls	
				July 27, 2017

Inspection Topic Summary

NOTE:	Y=Inspected	N=Not Inspected	R =Comments Noted	V=Violation Issued	NA=Not Applicable

- ${\bf N}\;$ Air Resource Protection
- **R** Availability of Records
- N Backfill & Grading
- ${\bf N}\,$ Excess Spoil and Dev. Waste
- \boldsymbol{N} Explosives
- **R** Fish & Wildlife
- **N** Hydrologic Balance
- ${\bf N}\,$ Gen. Compliance With Mine Plan
- N Other
- N Processing Waste

- **R** Roads
- **R** Reclamation Success
- **R** Revegetation
- N Subsidence
- ${\bf N}\,$ Slides and Other Damage
- N Support Facilities On-site
- **R** Signs and Markers
- N Support Facilities Not On-site
- **N** Special Categories Of Mining
- N Topsoil

COMMENTS

This was a complete inspection of the Coal Ridge No.1 Mine conducted by Brock Bowles of the Colorado Division of Reclamation, Mining and Safety. The operator was not present for this inspection. The weather conditions were overcast and warm. The temperature was approximately 80F and the ground was dry.

AVAILABILITY OF RECORDS - Rule 5.02.4(1):

All required records were on file and available for review at the Garfield County Clerk and Recorders Office in Glenwood Springs. The insurance certificate expires this month and needs to be updated. Please see the availability of records checklist at the end of this report.

FISH and WILDLIFE – Rule 4.18:

Five grouse were flushed out from under sagebrush during the inspection. The species of grouse was not determined.

ROADS – Rule 4.03 Construction 4.03.1(3)/4.03.2(3) Drainage 4.03.1(4)/4.03.2(4) Surfacing and Maintenance 4.03.1(5) and (6)/4.03.2(5) and (6) Reclamation 4.03.1(7)/4.03.2(7):

The road was in good condition. There were no rills or gullies in the road.

RECLAMATION SUCCESS - Rule 4.15, Rule 3:

No cattle were seen on the mine area and the electric fence was not in place.

REVEGETATION – Rule 4.15

Vegetative Cover; Timing:

A wildfire burned approximately 100 acres 0.5 mile west of the Coal Ridge Mine on July 3, 2017 (photo 1). About 75 of those acres were within the permit boundary. There were no mine related surface disturbances within the burned area.

Firefighters cut a fire break through undisturbed and reclaimed areas of the Coal Ridge Mine (photo 2). The fire Number of <u>Partial</u> Inspection this Fiscal Year: 0 Number of Complete Inspections this Fiscal Year: 1 break is on the west side of the mine disturbance area and its exact location was documented using a handheld GPS (photo 1). The overall length is 1250' and the width varies from 8' to 30'. The total disturbance is 0.55 acres in size and 0.14 acres of that disturbance was in reclaimed vegetation. The vegetation in the fire break was removed and pushed into small piles on the east side of the break (photo 3). The topsoil was disturbed in the fire break area but remained in place (photo 4). Rocks from the road area were pushed below the road into reclaimed pasture (photo 5). The reclaimed pasture has a post mine land use of wildlife habitat.

SIGNS AND MARKERS – Rule 4.02:

The mine entrance sign was in place with all the required information.

The disturbance boundary markers were in place.

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.



PHOTOGRAPHS

Photo 1 – Wildfire Burned Area

Photo 2 - Fire Break Looking North



Photo 3 – Vegetation Pushed to Side

Photo 4 – Topsoil Was Not Removed



Photo 5 – Fire Break Below the Road

AVAILABILITY OF RECORDS

PERMIT RECORDS

PERMIT RECORDS		HYDROLOGIC RECORDS	
DRMS Permit	X - 2021	NPDES Permit	X - 2017
Permit Application w/Revisions	Х	NPDES Records	NA
Findings Document	X - RN7	Stormwater Management Plan	NA
Insurance Certificate	X - 7/2017	SPCC Plan	NA
Bond Document	Х	MSHA Pond Inspections	NA
Phased Bond Release	Х		NA
Documents/Findings		State Engineer's Pond Inspection	
Air Emission Permits	NA	Quarterly Pond Inspections	NA
County Special Use Permits	NA	Annual Hydrology Reports	X - 2016
UG Mining Landowner Notification	NA	 Ground Water Monitoring 	NA
Subsidence Monitoring Reports	NA	• Surface Water Monitoring	NA
Subsidence Monitoring Data	NA	 Spring & Seep Monitoring 	NA
Rill & Gully Survey	X - 3/2017	Mine Water Discharge Monitoring	NA
Vegetation Monitoring Data	NA	• Mine Inflow Study	NA
Specific Variance Approvals	NA	• Water Consumption Records	NA
Annual Reclamation Reports	X - 2016	Well Permits	NA
Midterm Review Documents	X - MT7		
DRMS/OSM Inspection	Х		
Reports/Enforcement Actions (3			
Years)		BLASTING RECORDS	
Transfers/Succession of Operator	Х	Blasting Publication	NA
Temporary Cessation Notification	NA	Blasting Records (3 years)	NA
Reclamation Cost Estimate	Х	ATFE Explosives Permit	NA
CERTIFICATIONS		Blasting Variances	NA
Pond Certifications	NA	Pre-Blast Surveys	NA
Annual Certifications for	NA		
Impoundments			
Fill Certifications for Excess Spoil	NA	ADDITIONAL RECORDS	
or Underground Development Waste		(specify)	
 Quarterly Inspections 	NA		
 Compaction Testing 	NA		
 Final Certification 	NA		
Coal Processing Waste Banks	NA		
Haul Road Certifications	NA		
Access Road Certifications	NA		
COMMENTS:			