




**MINERALS PROGRAM INSPECTION REPORT**  
**PHONE: (303) 866-3567**

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

<b>MINE NAME:</b> Eagle-Gypsum Mine	<b>MINE/PROSPECTING ID#:</b> M-1984-041	<b>MINERAL:</b> Anhydrite, gypsum	<b>COUNTY:</b> Eagle
<b>INSPECTION TYPE:</b> Monitoring	<b>INSPECTOR(S):</b> Travis H. Marshall	<b>INSP. DATE:</b> August 29, 2017	<b>INSP. TIME:</b> 10:30
<b>OPERATOR:</b> American Gypsum Company LLC	<b>OPERATOR REPRESENTATIVE:</b> Jared Rhea	<b>TYPE OF OPERATION:</b> 112c - Construction Regular Operation	
<b>REASON FOR INSPECTION:</b> Normal I&E Program	<b>BOND CALCULATION TYPE:</b> None	<b>BOND AMOUNT:</b> \$1,429,700.00	
<b>DATE OF COMPLAINT:</b> NA	<b>POST INSP. CONTACTS:</b> U.S.BLM	<b>JOINT INSP. AGENCY:</b> None	
<b>WEATHER:</b> Clear	<b>INSPECTOR'S SIGNATURE:</b> 	<b>SIGNATURE DATE:</b> October 3, 2017	

**GENERAL INSPECTION TOPICS**

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>NA</u>
(PW) PROCESSING WASTE/TAILING---- <u>NA</u>	(SF) PROCESSING FACILITIES----- <u>Y</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>Y</u>	(RV) REVEGETATION---- <u>Y</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>NA</u>	(CI) COMPLETE INSP---- <u>Y</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>Y</u>	(SC) EROSION/SEDIMENTATION--- <u>Y</u>	(RS) RECL PLAN/COMP-- <u>Y</u>
(AT) ACID OR TOXIC MATERIALS----- <u>Y</u>	(OD) OFF-SITE DAMAGE----- <u>Y</u>	(ST) STIPULATIONS----- <u>NA</u>

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

### **OBSERVATIONS**

This inspection was conducted as part of the routine monitoring program established by the Colorado Division of Reclamation, Mining and Safety (DRMS). The Eagle-Gypsum Mine is a 112c permitted site consisting of 830 acres located approximately 1.5 miles north of Gypsum, Colorado. Brian Bloess and Jared Rhea of American Gypsum Company LLC and Jessica Lopez Pearce with the BLM Colorado River Valley Field Office were both present during the inspection.

The mine identification sign was in place and in compliance with rule 3.1.12. The sign is posted on the gate located at the main entrance to the mine.

The Class C list noxious weed Halogeton was observed near the reclaimed storage area. **In order to minimize the spread of Halogeton and aid in future revegetative success the operator must implement weed control efforts immediately.** The infestation is not considered a problem at this time but documentation of the infestation was noted in the 2016 inspection report and in this inspection report. The documentatio will be used as a tool to compare whether or not demonstrated weed control efforts have been implemented effectively during future inspections. The infestation is spreading and if no effort is made to control the spread of halogeton it will be cited as a problem and implementation of enforcement action will likely be initiated.

Adequate secondary containment for on-site fuel and toxic chemicals was observed during the inspection.

The construction of the new access was underway. The access is nearly complete and the only delay to the construction is generating enough material to bring the acess road to the required grade. The operator is required to provide "as built" drawings once the project is complete.

Active mining was observed in northeast section of the permit area. Large stockpiles of gypsum along with stockpiles of overburden were observed at various locations within the active mine area. Haul trucks, loaders and rotor-mills were observed working the mine floor.

Reclamation observed during the inspection was located on the slopes located north of the active mining area. The slopes are reclaimed and appear to be no steeper than 3H:1V. The vegetation observed included desirable established annual grass species along with slash placed perpendicular to the dip of the slope. Due to adequate vegetation and correctly placed woody debris the reclaimed slopes were void of any significant erosional features. Halogeton was also observed in this protion of the permit area.

Photos that show the conditions observed during the inspection are included at the end of this report.

No problems or violations were noted or observed during the August 29, 2017 inspection.

Responses to this inspection report should be directed to Travis Marshall at the Division of Reclamation, Mining and Safety, Grand Junction Field Office, 101 South 3rd Street, Room 301, Grand Junction, Colorado 81501, phone no. 970-241-2042.



**PHOTOGRAPHS**



**Inspection Contact Address**

Jared Rhea  
American Gypsum Company LLC  
740 Hwy 6  
Gypsum, CO 81637

CC: Jessica Lopez Pearce  
Bureau of Land Management  
Colorado River Valley Field Office  
2300 River Frontage Road  
Silt, CO 81652