



Seneca Coal Company
Peabody Energy
PO Box 670
36600 Routt County Road 27
Hayden, CO 81639

December 14, 2017
Jason Musick
Colorado Division of Reclamation, Mining and Safety
1313 Sherman Street
Denver, CO 80203

RE: Yoast Mine, Permit C-94-082, 4Q17 IIR

Dear Jason:

In accordance with Rule 4.05.9(17), please find enclosed the Yoast Mine Impoundment Inspection Report (IIR) and Impoundment Inspection Log (IIL) for Ponds: Pond #010, Pond #011, Pond #011A, Pond #012, Pond #012A, Pond #013, Pond #014 and Stock Tank ST-1.

Maintenance is required at Ponds: #10 (intake) and #012 (flume). Please contact me with any comments and/or questions.

Sincerely,

Miranda Blomquist

TNS/*tns*

Enclosure: Yoast IIR

Mining Area	Yeast Mine(Seneca Coal Co)	Facility Configuration	Cross-Valley Pond	Quarterly Impoundment Inspection Form
Date Inspected	10/17/2017	Date Last Inspected	8/17/2017	
Impoundment	Pond #010	Pond Location	NW¼ NE¼, Sec. 8, T5N, R87W	
NPDES ID No	CO-0000221 D.P. 010	Site Location	8.5 mi SE of Hayden, CO	
Owner's Rep	Miranda Kawcak	Inspector	Jason Herden	

Mark or Write in Appropriate Response:			COMMENTS
FEATURE	PROBLEM		
	YES (Above)	NO (Below)	
GENERAL			
Water Level (above or below principal spillway)	X		water level 0.15 feet above spillway
Existing Embankment Freeboard (10.1 ft)	10.1		
Outflow (gpm)	X		23.5
EROSION			
Rills & Gullies on Embankment		X	
Wave Erosion		X	
Spillway Erosion		X	
Burrows		X	
Other		X	
STRUCTURAL			
Differential Settling		X	
Cracks or Slides		X	
Seepage		X	
Other		X	
STRUCTURES			
Principal Spillway			
Clogged Orifice		X	Intake starting to rust out but still functional
Clogged or Damaged Culvert	X		
Damaged Headgate		NA	
Emergency Spillway			
Erosion		X	
Riprap		X	
Clogged or Damaged Culvert		X	
Other		X	
MAINTENANCE			
Maintenance Required	X		See comment above
Maintenance Performed		X	
Additional Comments		X	

Mining Area	Yeast Mine(Seneca Coal Co)	Facility Configuration	Cross-Vally Pond	Quarterly Impoundment Inspection Form
Date Inspected	10/18/2017	Date Last Inspected	8/17/2017	
Impoundment	Pond #011	Pond Location	NW¼ SW¼, Sec. 16, T5N, R87W	
NPDES ID No	CO-0000221 D.P.011	Site Location	8.5 mi SE of Hayden, CO	
Owner's Rep	Miranda Kawcak	Inspector	Jason Herden	
Mark or Write in Appropriate Response:				
FEATURE	PROBLEM		COMMENTS	
	YES (Above)	NO (Below)		
GENERAL				
Water Level (above or below principal spillway)		X	Water level 7.0 feet below top of pipe	
Existing Embankment Freeboard (5.1 ft)	5.2			
Outflow (gpm)		X		
EROSION				
Rills & Gullies on Embankment		X		
Wave Erosion		X		
Spillway Erosion		X		
Burrows		X		
Other		X		
STRUCTURAL				
Differential Settling		X		
Cracks or Slides		X		
Seepage		X		
Other		X		
STRUCTURES				
Principal Spillway				
Clogged Orifice		X		
Clogged or Damaged Culvert		X		
Damaged Headgate		NA		
Emergency Spillway				
Erosion		X		
Riprap		X		
Clogged or Damaged Culvert		X		
Other		X		
MAINTENANCE				
Maintenance Required		X		
Maintenance Performed		X		
Additional Comments		X		

Mining Area	Yoast Mine(Seneca Coal Co)	Facility Configuration	Cross-Vally Pond	Quarterly Impoundment Inspection Form
Date Inspected	10/17/2017	Date Last Inspected	8/17/2017	
Impoundment	Pond #011A	Pond Location	SWX NWX, Sec. 16, T5N, R87W	
NPDES ID No	N/A	Site Location	8.5 mi SE of Hayden, CO	
Owner's Rep	Miranda Kawcak	Inspector	Jason Herden	
Mark or Write in Appropriate Response:				
FEATURE	PROBLEM		COMMENTS	
	YES (Above)	NO (Below)		
GENERAL				
Water Level (above or below principal spillway)		X	Water level is 2.3 feet below outlet pipe	
Existing Embankment Freeboard (4.6 ft)	5.3			
Outflow (gpm)		X		
EROSION				
Rills & Gullies on Embankment		X		
Wave Erosion		X		
Spillway Erosion		X		
Burrows		X		
Other		X		
STRUCTURAL				
Differential Settling		X		
Cracks or Slides		X		
Seepage		X		
Other		X		
STRUCTURES				
Principal Spillway				
Clogged Orifice		X		
Clogged or Damaged Culvert		X		
Damaged Headgate		NA		
Emergency Spillway				
Erosion		X		
Riprap		X		
Clogged or Damaged Culvert		X		
Other		X		
MAINTENANCE				
Maintenance Required		X		
Maintenance Performed		X		
Additional Comments		X		

Top of Sediment Storage = 2.1 feet below top of pipe

Mining Area	Yoast Mine(Seneca Coal Co)	Facility Configuration	Cross-Vally Pond	Quarterly Impoundment Inspection Form
Date Inspected	10/17/2017	Date Last Inspected	8/17/2017	
Impoundment	Pond #012	Pond Location	NEX NWX, Sec. 19, T5N, R87W	
NPDES ID No	CO-0000221 D.P. 012	Site Location	8.5 mi SE of Hayden, CO	
Owner's Rep	Miranda Kawcak	Inspector	Jason Herden	

Mark or Write in Appropriate Response:			
FEATURE	PROBLEM		COMMENTS
	YES (Above)	NO (Below)	
GENERAL			
Water Level (above or below principal spillway)	X		Water level 0.06 feet above spillway
Existing Embankment Freeboard (9.0 ft)	9		
Outflow (gpm)	X		25.8
EROSION			
Rills & Gullies on Embankment		X	
Wave Erosion		X	
Spillway Erosion		X	
Burrows		X	
Other		X	
STRUCTURAL			
Differential Settling		X	
Cracks or Slides		X	
Seepage		X	
Other		X	
STRUCTURES			
Principal Spillway			
Clogged Orifice		X	
Clogged or Damaged Culvert		X	
Damaged Headgate		NA	
Emergency Spillway			
Erosion		X	
Riprap		X	
Clogged or Damaged Culvert		X	
Other		X	
MAINTENANCE			
Maintenance Required	X		Erosion behind and underneath flume
Maintenance Performed		X	
Additional Comments		X	

Mining Area	Yoast Mine(Seneca Coal Co)	Facility Configuration	Cross-Vally Pond	Quarterly Impoundment Inspection Form
Date Inspected	10/17/2017	Date Last Inspected	8/17/2017	
Impoundment	Pond #012A	Pond Location	NEX NW¼, Sec. 19, T5N, R87W	
NPDES ID No	N/A	Site Location	8.5 mi SE of Hayden, CO	
Owner's Rep	Miranda Kawcak	Inspector	Jason Herden	
Mark or Write in Appropriate Response:				
FEATURE	PROBLEM		COMMENTS	
	YES (Above)	NO (Below)		
GENERAL				
Water Level (above or below principal spillway)		X	Water level 0.9 feet below spillway	
Existing Embankment Freeboard (4.6 ft)	6.2			
Outflow (gpm)		X		
EROSION				
Rills & Gullies on Embankment		X		
Wave Erosion		X		
Spillway Erosion		X		
Burrows		X		
Other		X		
STRUCTURAL				
Differential Settling		X		
Cracks or Slides		X		
Seepage		X		
Other		X		
STRUCTURES				
Principal Spillway				
Clogged Orifice		X		
Clogged or Damaged Culvert		X		
Damaged Headgate		NA		
Emergency Spillway				
Erosion		X		
Riprap		X		
Clogged or Damaged Culvert		X		
Other		X		
MAINTENANCE				
Maintenance Required		X		
Maintenance Performed		X		
Additional Comments		X		

Mining Area	Yoast Mine(Seneca Coal Co)	Facility Configuration	Cross-Vally Pond	Quarterly Impoundment Inspection Form
Date Inspected	10/17/2017	Date Last Inspected	8/17/2017	
Impoundment	Pond #013	Pond Location	SE¼ NW¼, Sec. 19, T5N, R87W	
NPDES ID No	CO-0000221 D.P. 013	Site Location	8.5 mi SE of Hayden, CO	
Owner's Rep	Miranda Kawcak	Inspector	Jason Herden	

Mark or Write in Appropriate Response:			COMMENTS
FEATURE	PROBLEM		
	YES (Above)	NO (Below)	
GENERAL			
Water Level (above or below principal spillway)		X	water level 1.2 feet below outlet pipe
Existing Embankment Freeboard (4.0 ft)	4		
Outflow (gpm)		X	
EROSION			
Rills & Gullies on Embankment		X	
Wave Erosion		X	
Spillway Erosion		X	
Burrows		X	
Other		X	
STRUCTURAL			
Differential Settling		X	
Cracks or Slides		X	
Seepage		X	
Other		X	
STRUCTURES			
Principal Spillway			
Clogged Orifice		X	
Clogged or Damaged Culvert		X	
Damaged Headgate		NA	
Emergency Spillway			
Erosion		X	
Riprap		X	
Clogged or Damaged Culvert		X	
Other		X	
MAINTENANCE			
Maintenance Required		X	
Maintenance Performed		X	
Additional Comments		X	

Mining Area	Yoast Mine(Seneca Coal Co)	Facility Configuration	Cross-Vally Pond	Quarterly Impoundment Inspection Form
Date Inspected	10/17/2017	Date Last Inspected	8/17/2017	
Impoundment	Pond #014	Pond Location	NEX SWK, Sec. 19, T5N, R87W	
NPDES ID No	CO-0000221 D.P. 014	Site Location	8.5 mi SE of Hayden, CO	
Owner's Rep	Miranda Kawcak	Inspector	Jason Herden	

Mark or Write in Appropriate Response:			COMMENTS
FEATURE	PROBLEM		
	YES (Above)	NO (Below)	
GENERAL			
Water Level (above or below principal spillway)		X	water level 1.1 feet below outlet pipe
Existing Embankment Freeboard (6.8 ft)	6.8		
Outflow (gpm)		X	
EROSION			
Rills & Gullies on Embankment		X	
Wave Erosion		X	
Spillway Erosion		X	
Burrows		X	
Other		X	
STRUCTURAL			
Differential Settling		X	
Cracks or Slides		X	
Seepage		X	
Other		X	
STRUCTURES			
Principal Spillway			
Clogged Orifice		X	
Clogged or Damaged Culvert		X	
Damaged Headgate		NA	
Emergency Spillway			
Erosion		X	
Riprap		X	
Clogged or Damaged Culvert		X	
Other		X	
MAINTENANCE			
Maintenance Required		X	
Maintenance Performed		X	
Additional Comments		X	

Mining Area	Yost Mine(Seneca Coal Co)	Facility Configuration	Stockpond	Quarterly Impoundment Inspection Form
Date Inspected	10/18/2017	Date Last Inspected	8/17/2017	
Impoundment	Stock Tank ST-1	Pond Location	SWX Sec. 20, T5N, R87W	
NPDES ID No	N/A	Site Location	8.5 mi SE of Hayden, CO	
Owner's Rep	Miranda Kawcak	Inspector	Jason Herden	
Mark or Write in Appropriate Response:				
FEATURE	PROBLEM		COMMENTS	
	YES (Above)	NO (Below)		
GENERAL				
Water Level (above or below principal spillway)		X	Water level is 2.0 feet below spillway	
EROSION				
Rills & Gullies on Embankment		X		
Wave Erosion		X		
Spillway Erosion		X		
Burrows		X		
Other		X		
STRUCTURAL				
Differential Settling		X		
Cracks or Slides		X		
Seepage		X		
Other		X		
STRUCTURES				
Principal Spillway				
Clogged Orifice		NA		
Clogged or Damaged Culvert		NA		
Damaged Headgate		NA		
Emergency Spillway				
Erosion		X		
Riprap		X		
Clogged or Damaged Culvert		NA		
Other		X		
MAINTENANCE				
Maintenance Required		X		
Maintenance Performed		X		
Additional Comments		X		

IMPOUNDMENT INSPECTION LOG

JOB DATA

JOB NAME: PEC Hydrologic Support Services	CLIENT: Peabody	LOCATION: Routt County, CO
JOB(s): 2016-037 T1-SCC, T2-PSCM		

FLOW DATA

SITE ID	COMPANY	MINE	DATE	TIME	WATER LEVEL (FT)	OUTFLOW (GPM)	OBSERVATIONS	MAINTENANCE (Y/N)
002	Sage Creek	Sage Creek	10-17-17	15:10	0.09	127.1		N
003	Sage Creek	Sage Creek	10-17-17	14:45	0.08	7.2	animal burrows on dam	N
004	Sage Creek	Sage Creek	10-17-17	15:35	0.26	30.1		N
Lower Sump	Sage Creek	Sage Creek	10-18-17	09:35	0.05	18		N
PECOCO	Sage Creek	Sage Creek	10-18-17	10:15	0.07	51		N
Portal Sump 1	Sage Creek	Sage Creek	10-18-17	09:45	0.03	1		N
Portal Sump 2	Sage Creek	Sage Creek	10-18-17	09:55	—	—	not pumping	N
Spill Control 2	Sage Creek	Sage Creek	10-18-17	09:25	—	—	Dry	N
Truck Wash	Sage Creek	Sage Creek	10-18-17	09:15	—	—	Dry	N
Upper Sump	Sage Creek	Sage Creek	10-18-17	10:25	0.05	44		N
001	Seneca	Hayden Gulch	10-18-17	08:00	-3.3	—	NO Flow	N
002	Seneca	Hayden Gulch	10-18-17	08:10	—	—	Dry	N
005	Seneca	Seneca II West	10-17-17	11:05	-1.9	—	NO Flow spring on dam, no flow	N
006	Seneca	Seneca II West	10-17-17	08:55	0.15	32.7	big stuff on S. side, no impact	N
009	Seneca	Seneca II West	10-17-17	11:35	-3.4	—	NO Flow spring on dam	N
015	Seneca	Seneca II West	10-17-17	12:00	-1.6	—	NO Flow, Fixed stand pipe	N
016	Seneca	Seneca II West	10-17-17	09:15	0.10	21.6	small leak under flume	Y
017	Seneca	Seneca II West	10-17-17	09:40	0.06	8.0	water leaking under flume	Y
T-1	Seneca	Seneca II West	10-17-17	09:05	—	—	Dry	N
T-18	Seneca	Seneca II West	10-17-17	10:50	-1.6	—	NO Flow	N
T-2	Seneca	Seneca II West	10-17-17	10:45	-2.3	—	NO Flow	N
T-20	Seneca	Seneca II West	10-17-17	10:55	-2.6	—	NO Flow	N
T-22	Seneca	Seneca II West	10-17-17	11:00	-0.9	—	NO Flow	N
T-24	Seneca	Seneca II West	10-17-17	11:15	—	—	Dry	N
T-25	Seneca	Seneca II West	10-17-17	09:50	—	—	gone	N
T-26	Seneca	Seneca II West	10-17-17	10:20	-2.0	—	NO Flow	N

008

10-17-17 16:20 0.2 15.5 outlet pipe slight leak N

