




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: C Road Pit	MINE/PROSPECTING ID#: M-2016-050	MINERAL: Sand and gravel	COUNTY: Mesa
INSPECTION TYPE: Monitoring	INSPECTOR(S): Amy C. Yeldell	INSP. DATE: February 23, 2018	INSP. TIME: 11:30
OPERATOR: Parkerson Construction, Inc.	OPERATOR REPRESENTATIVE: Greg Monger	TYPE OF OPERATION: 112c - Construction Regular Operation	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: None	BOND AMOUNT: \$241,201.40	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
WEATHER: Windy	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: March 7, 2018	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>NA</u>
(PW) PROCESSING WASTE/TAILING---- <u>NA</u>	(SF) PROCESSING FACILITIES----- <u>NA</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>Y</u>	(RV) REVEGETATION---- <u>NA</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>NA</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>Y</u>	(ST) STIPULATIONS----- <u>Y</u>
(AT) ACID OR TOXIC MATERIALS----- <u>NA</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted as part of the Colorado Division of Reclamation, Mining and Safety (Division) normal monitoring program. The C Road Pit is a 112c permitted site that includes a total of 84.90 permitted acres. The site located at the intersection of C Road and 31 Road in Grand Junction, CO. Greg Monger of Parkerson Construction, Inc. represented the operator and accompanied Amy Yeldell of the Division conducted the inspection.

The mine identification sign and affected area boundary markers are in place and in compliance with Rule 3.1.12. A sign is posted as you enter the permit boundary. The permit boundary is delineated by fences in some areas and t-post in areas adjacent to the 31 Road Pit (M-1987-178).

This site was active at the time of the inspection. This is a newly activated permit. Approximately an acre has been stripped so far in the northwest corner of phase 1. This site has a maximum disturbance of 40 acres. Material was being excavated and loaded to be hauled off site. The near vertical highwall is approximately 20 feet tall and 300 feet long.

For the time being the C Road Pit is using the access road for the 31 Road Pit since that's where the scale is located. Material was weighed prior to it leaving the site. Once mining progresses and 31 Road Pit is mined out the scale will be moved and the more western access road will be used. Both pits are owned and operated by Parkerson Construction, Inc.

No equipment, fuel or structures are located on site. There are no stockpiles or exposed water. No interim or final reclamation has been complete. The topsoil pile did not appear to be reseeded yet. The site is clean and free of trash and other miscellaneous debris.

Since the inspection a Succession of Operators application has been submitted to transfer the pit to Kilgore Companies LLC dba Elam Construction. This inspection will also serve as the SO-1 inspection.

The Division currently requires a financial warranty amount of \$241,201.40 for this site.

No problems or violations were noted during this inspection.

Responses to this inspection report should be directed to: Amy Yeldell at the Division of Reclamation, Mining and Safety, 1313 Sherman St., Room 215, Denver, CO 80203. Direct contact can be made by phone at 970-254-8511 or via email at amy.yeldell@state.co.us

PHOTOGRAPHS









Inspection Contact Address

Greg Monger
Parkerson Construction, Inc.
710 S. 15th Street
Grand Junction, CO 81501

Jon Muller
Kilgore Companies LLC dba Elam Construction
556 Struthers Ave.
Grand Junction, 81501 CO

Enclosure

CC:
Russ Means, Senior EPS, Grand Junction DRMS