




**MINERALS PROGRAM INSPECTION REPORT**  
**PHONE: (303) 866-3567**

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

<b>MINE NAME:</b> East Bradbury Pit	<b>MINE/PROSPECTING ID#:</b> M-2010-016	<b>MINERAL:</b> Sand and gravel	<b>COUNTY:</b> Mesa
<b>INSPECTION TYPE:</b> Monitoring	<b>INSPECTOR(S):</b> Amy C. Yeldell	<b>INSP. DATE:</b> March 20, 2018	<b>INSP. TIME:</b> 09:00
<b>OPERATOR:</b> Grand Junction Pipe & Supply Co.	<b>OPERATOR REPRESENTATIVE:</b> Jon Muller	<b>TYPE OF OPERATION:</b> 112c - Construction Regular Operation	
<b>REASON FOR INSPECTION:</b> Normal I&E Program	<b>BOND CALCULATION TYPE:</b> None	<b>BOND AMOUNT:</b> \$107,139.00	
<b>DATE OF COMPLAINT:</b> NA	<b>POST INSP. CONTACTS:</b> None	<b>JOINT INSP. AGENCY:</b> None	
<b>WEATHER:</b> Windy	<b>INSPECTOR'S SIGNATURE:</b> 	<b>SIGNATURE DATE:</b> March 29, 2018	

**GENERAL INSPECTION TOPICS**

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>NA</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>NA</u>	(EX) EXPLOSIVES----- <u>NA</u>
(PW) PROCESSING WASTE/TAILING---- <u>NA</u>	(SF) PROCESSING FACILITIES----- <u>NA</u>	(TS) TOPSOIL----- <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>N</u>	(FW) FISH & WILDLIFE----- <u>Y</u>	(RV) REVEGETATION---- <u>NA</u>
(SM) SIGNS AND MARKERS----- <u>N</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>NA</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>Y</u>	(ST) STIPULATIONS----- <u>Y</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>NA</u>	

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

### **OBSERVATIONS**

This inspection was conducted as part of the Colorado Division of Reclamation, Mining and Safety (Division) normal monitoring program. The East Bradbury Pit is a 112c permitted site that includes a total of 129 permitted acres. The site located approximately six miles southeast of Whitewater, Colorado and is accessed from Highway 50. Jon Muller of Grand Junction Pipe & Supply Co. represented the operator and accompanied Amy Yeldell of the Division conducted the inspection.

No mining has taken place at this site. There are no stockpiles, equipment, fuel or structures on site. Some trash was observed however it does not appear to be due to mining and therefore is not cited as a problem.

There is a locked gate at the access road the pit from Highway 50. There are no acceleration or deceleration lanes making access difficult. There was no mine sign posted at the entrance.

Areas that appeared to be previously disturbed had a higher density of noxious plants as compare to the undisturbed areas. Unless this disturbance is mining related the landowner is responsible for weed management not the operator. In general this area has a very low vegetation density, especially for desirable native plants.

The Division currently requires a financial warranty amount of \$107,139 for this site.

No problems or violations were noted during this inspection.

Responses to this inspection report should be directed to: Amy Yeldell at the Division of Reclamation, Mining and Safety, 1313 Sherman St., Room 215, Denver, CO 80203. Direct contact can be made by phone at 970-254-8511 or via email at amy.yeldell@state.co.us

**PHOTOGRAPHS**









**Inspection Contact Address**

Jon Muller  
Grand Junction Pipe & Supply Co.  
556 Struthers Ave.  
Grand Junction, CO 81501

Enclosure

CC:  
Russ Means, Senior EPS, Grand Junction DRMS