


**COLORADO**Division of Reclamation,
Mining and Safety

Department of Natural Resources

MINERALS PROGRAM INSPECTION REPORT**PHONE: (303) 866-3567**

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: LGPD2-2	MINE/PROSPECTING ID#: P-2015-021	MINERAL: Quartz ,fluorine, fluorite	COUNTY: Park
INSPECTION TYPE: Monitoring	INSPECTOR(S): Michael A. Cunningham	INSP. DATE: April 10, 2018	INSP. TIME: 11:30
OPERATOR: JC Minerals LLC	OPERATOR REPRESENTATIVE: John Crowley	TYPE OF OPERATION: MP - Mineral Prospecting	
REASON FOR INSPECTION: Normal I&e Program	BOND CALCULATION TYPE: Complete Bond	BOND AMOUNT: \$2,625.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
WEATHER: Clear	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: June 6, 2018	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>N</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>N</u>
(HB) HYDROLOGIC BALANCE----- <u>N</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>N</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>Y</u>
(SM) SIGNS AND MARKERS----- <u>N</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>N</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

The inspection was conducted by Michael Cunningham of the Division of Reclamation, Mining and Safety (Division). John Crowley and Michael Royer were present on behalf of JC Minerals LLC. The LGPD2-2 prospect site is located in Park County, approximately 1.2 miles north of Lake George in the Pike-San Isabel National Forest. The commodities of interest are quartz, amazonite and fluorite.

The Operator has completed prospecting and the site is in the final stage of reclamation. The Operator and the Division visited the five prospecting trenches approved for this operation. As noted in the previous inspection report, one of the five prospecting trenches was created by un-permitted prospectors. However, the Operator has performed reclamation at all five of the excavated areas. The reclaimed prospecting trenches have been graded to the natural slopes and have been broadcast seeded. The Division observed germination of some of the planted grass species. However, additional time will be required to establish vegetation which is capable of self-regeneration without further aid from the Operator. The Operator should continue to monitor the success of the vegetation. If additional grass has not germinated by the fall, the Operator should consider a late season reseeding of the prospecting sites.

During the inspection, the Division encountered two men who were digging in one of the Operator's reclaimed excavation areas. The men identified themselves as Mr. Justin Odryna and Henry (no last name provided). The men were using hand tools and had created a small excavation, approximately three feet wide and one foot deep. The Division informed the men they were trespassing on the Operator's unpatented claim. In addition, they were informed of the requirements for prospecting and mining. Mr. Odryna and Henry agreed to fill in the hole they had excavated before they vacated the premises.

The Division holds a financial warranty in the amount of \$2,625.00, which is adequate to complete reclamation of the site.

This concluded the inspection.

Inspection Contact Address

John Crowley
JC Minerals LLC
382 McArthur Dr.
Lone Tree, CO 80124

PHOTOGRAPHS



1. Reclaimed prospect site, disturbance created by un-permitted prospectors.



2. Reclaimed prospect site, where un-permitted prospector were encountered.



3. Reclaimed prospect site, early establishment of vegetation.



4. Reclaimed prospect site, early establishment of vegetation.