

# MINERALS PROGRAM INSPECTION REPORT PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE/PROSPECTING ID#:	MINERAL:	COUNTY:		
M-2016-084	Gold and silver	Gunnison		
<b>INSPECTOR(S):</b>	INSP. DATE:	INSP. TIME:		
Dustin M. Czapla	June 19, 2018	14:00		
OPERATOR REPRESENTATIVE:	TYPE OF OPERATION:			
Jake Wilkinson	110(2) - Hard Rock Limited Impact			
REASON FOR INSPECTION: BOND CALCULATION TYPE: BOND AMOUNT:				
BOND CALCULATION TYPE:	BOND AMOUNT:			
None	\$7,600.00			
POST INSP. CONTACTS:	JOINT INSP. AGE	NCY:		
None	None			
INSPECTOR'S SIGNATURE:	SIGNATURE DAT	<b>E:</b>		
06	July 9, 2018			
The				
	M-2016-084 INSPECTOR(S): Dustin M. Czapla OPERATOR REPRESENTATIVE: Jake Wilkinson  BOND CALCULATION TYPE: None POST INSP. CONTACTS: None	M-2016-084  INSPECTOR(S): Dustin M. Czapla  OPERATOR REPRESENTATIVE: Jake Wilkinson  BOND CALCULATION TYPE: None POST INSP. CONTACTS: None INSPECTOR'S SIGNATURE:  Gold and silver INSP. DATE: TYPE OF OPERA 110(2) - Hard Rock  BOND AMOUNT: \$7,600.00 JOINT INSP. AGE None INSPECTOR'S SIGNATURE:		

#### **GENERAL INSPECTION TOPICS**

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS <u>Y</u>	(FN) FINANCIAL WARRANTY N	(RD) ROADS <u>N</u>
(HB) HYDROLOGIC BALANCE <u>N</u>	(BG) BACKFILL & GRADING <u>N</u>	(EX) EXPLOSIVES <u>N</u>
(PW) PROCESSING WASTE/TAILING N	(SF) PROCESSING FACILITIES $\underline{N}$	(TS) TOPSOIL <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE $\underline{N}$	(RV) REVEGETATION <u>N</u>
(SM) SIGNS AND MARKERS <u>Y</u>	(SP) STORM WATER MGT PLAN N	(RS) RECL PLAN/COMP N
(ES) OVERBURDEN/DEV. WASTE N	(SC) EROSION/SEDIMENTATION $\underline{Y}$	(ST) STIPULATIONS <u>N</u>
(AT) ACID OR TOXIC MATERIALS N	(OD) OFF-SITE DAMAGE <u>N</u>	

 $Y = Inspected \ and \ found \ in \ compliance \ / \ N = Not \ inspected \ / \ NA = Not \ applicable \ to \ this \ operation \ / \ PB = Problem \ cited \ / \ PV = Possible \ violation \ cited \ A = Not \ applicable \ to \ this \ operation \ / \ PB = Problem \ cited \ / \ PV = Possible \ violation \ violation \ violation \ / \ PV = Possible \ violation \ v$ 

PERMIT #: M-2016-084 INSPECTOR'S INITIALS: DMC INSPECTION DATE: June 19, 2018

### **OBSERVATIONS**

This was a routine monitoring inspection. Jake Wilkinson, representing the operator, was present during the inspection. Photographs are included with this report in order to illustrate some of the conditions observed.

The Sacramento Access Tunnel is located approximately five miles north of Ohio City and accessed from FR 879. The site is a 110(2) operation that includes a total of 5.55 permitted acres. The Division currently holds a financial warranty amount of \$7,600.00 for this site. The application was approved February 10, 2017. The only activity that has occurred at the site so far is some minor clearing/grading in the portal area.

Adequate mine identification signage was noted at the entrance to the site.

No problems or violations were noted during this inspection.

Responses to this inspection report should be directed to Dustin Czapla at the Division of Reclamation, Mining and Safety, Grand Junction Field Office, 101 South 3<sup>rd</sup> Street, Room 301, Grand Junction, Colorado 81501, phone number (970) 243-6299.

## **PHOTOGRAPHS**





#### **Inspection Contact Address**

Jake Wilkinson CRG Mining, LLC 510 S. Wisconsin St. Gunnison, CO 81230