

Division of Reclamation, Mining and Safety
1313 Sherman St., Room 215
Denver, Colorado 80203

Subject: Annual Report

No new mining was conducted this year. Activity was limited to maintenance of the buildings, storm water management and ground control to protect the existing hoist shed and shaft house from rain and snow melt water. The steep bank behind the hoist shed kept sloughing off and causing a build up of dirt and rocks against the metal building. A sturdy barrier was constructed some years ago to stop this from happening but it was not evident on my copy of the last map. This new map shows this barrier. Other than that, the old map is complete.

Enclosures: Copy of map, Check for ^{\$ 172.00}~~\$86.00~~, Annual report.

Sincerely yours

Harry D. Covey, Owner, Operator Permit No. M-1988-081