




MINERALS PROGRAM INSPECTION REPORT

PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Peroulis Brothers Snake River Pit	MINE/PROSPECTING ID#: M-2009-079	MINERAL: Gravel and sand	COUNTY: Moffat
INSPECTION TYPE: Monitoring	INSPECTOR(S): Amy C. Yeldell	INSP. DATE: August 7, 2018	INSP. TIME: 13:15
OPERATOR: Precision Excavating, Inc.	OPERATOR REPRESENTATIVE: None	TYPE OF OPERATION: 112c - Construction Regular Operation	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: None	BOND AMOUNT: \$199,600.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: DRMS	JOINT INSP. AGENCY: None	
WEATHER: Clear	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: August 14, 2018	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>N</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>NA</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>Y</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>Y</u>	(RV) REVEGETATION---- <u>Y</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>Y</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>Y</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>NA</u>	(OD) OFF-SITE DAMAGE----- <u>Y</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted as part of the Colorado Division of Reclamation, Mining and Safety normal monitoring program. The Peroulis Brothers Snake River Pit is a 112c permitted site that includes a total of 101 permitted acres. It is located approximately 39 miles northeast of Craig and is accessed from Moffat County Road 21. There was no representative from Precision Excavating, Inc. on site but they were contacted prior to the inspection. Amy Yeldell of the Division conducted the inspection.

The site was inactive at the time of the inspection. On February 1, 2016 TC-1 was approved which was retroactive to begin on October 9, 2015. The site should resume activity or begin TC-2 on or before 10-9-2020.

The mine identification sign and affected area boundary markers remain in place and in compliance with Rule 3.1.12. A scale and scale house remain on site. No other equipment, fuel, structures or debris are on site.

There was some Halogeton and Russian Thistle on site. They appear to be knocked down. There was no evidence of dye to indicate weed treatment so the Division is unsure if wilting is due to the heat or weed treatments. Overall there appears to be less Halogeton as compared to previous inspections but slightly more Russian Thistle was present.

The far southern affected lands where several test holes were dug, appear to be self-reclaiming with native vegetation. Overall the site is stable with no signs of erosion. Several stockpiles remain on site which are stored neatly with slopes no steeper than 2:1.

The Division currently holds a financial warranty in the amount of \$199,600.

Responses to this inspection report should be directed to: Amy Yeldell at the Division of Reclamation, Mining and Safety, 1313 Sherman St., Room 215, Denver, CO 80203. Direct contact can be made by phone at 970-254-8511 or via email at amy.yeldell@state.co.us

Inspection Contact Address

David Zehner
Precision Excavating, Inc.
195 W. Jefferson
Hayden, CO 81639

Enclosure

EC: Wally Erickson, Senior EPS, GJFO DRMS

PHOTOGRAPHS





