

MINERALS PROGRAM INSPECTION REPORT PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:		MINE/PROSPECTING ID#:	MINERAL:	COUNTY:		
Half Moon Site		P-2015-014	Sand and gravel	Lake		
INSPECTION TYPE:		INSPECTOR(S):	INSP. DATE:	INSP. TIME:		
Monitoring		Dustin M. Czapla	August 8, 2018	18:00		
OPERATOR:		OPERATOR REPRESENTATIVE:	TYPE OF OPERATION:			
City of Leadville			MP - Mineral Prospecting			
REASON FOR INSPECTION:		BOND CALCULATION TYPE:	BOND AMOUNT:			
Normal I&E Program		NA	\$0.00			
DATE OF COMPLAINT:		POST INSP. CONTACTS:	JOINT INSP. AGENCY:			
NA		None	None			
WEATHER:	INSPECTOR'S SIGNATURE:		SIGNATURE DATE:			
Clear	De		August 17, 2018			

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS <u>N</u>	(FN) FINANCIAL WARRANTY N	(RD) ROADS <u>N</u>
(HB) HYDROLOGIC BALANCE <u>N</u>	(BG) BACKFILL & GRADING \underline{Y}	(EX) EXPLOSIVES N
(PW) PROCESSING WASTE/TAILING N	(SF) PROCESSING FACILITIES \underline{N}	(TS) TOPSOIL <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- Y	(FW) FISH & WILDLIFE \underline{N}	(RV) REVEGETATION <u>Y</u>
(SM) SIGNS AND MARKERS <u>N</u>	(SP) STORM WATER MGT PLAN N	(RS) RECL PLAN/COMP <u>Y</u>
(ES) OVERBURDEN/DEV. WASTE N	(SC) EROSION/SEDIMENTATION \underline{N}	(ST) STIPULATIONS <u>N</u>
(AT) ACID OR TOXIC MATERIALS N	(OD) OFF-SITE DAMAGE <u>N</u>	

 $Y = Inspected \ and \ found \ in \ compliance \ / \ N = Not \ inspected \ / \ NA = Not \ applicable \ to \ this \ operation \ / \ PB = Problem \ cited \ / \ PV = Possible \ violation \ cited \ A = Not \ applicable \ to \ this \ operation \ / \ PB = Problem \ cited \ / \ PV = Possible \ violation \ cited \ A = Not \ applicable \ to \ this \ operation \ / \ PB = Problem \ cited \ / \ PV = Possible \ violation \ cited \ A = Not \ applicable \ to \ this \ operation \ / \ PB = Problem \ cited \ / \ PV = Possible \ violation \ cited \ A = Not \ applicable \ to \ this \ operation \ / \ PB = Problem \ cited \ / \ PV = Possible \ violation \ violation \ cited \ / \ PV = Possible \ violation \ vio$

PERMIT #: P-2015-014 INSPECTOR'S INITIALS: DMC INSPECTION DATE: August 8, 2018

OBSERVATIONS

This inspection was conducted as part of the Division of Reclamation, Mining and Safety's (Division) normal monitoring program. A representative for the operator was not present. Photographs are included with this report in order to illustrate the conditions observed.

The Halfmoon Site is located approximately five miles southwest of Leadville and accessed from CR 11A. This is an exploration operation that was authorized to drill three boreholes. According to the operator's abandonment report the holes were drilled and reclaimed in June 2015. Pursuant to Rule 4.1.2 (2), a financial warranty is not required for this site.

This inspection confirmed that there is no unreclaimed disturbance at the site. The operator should be released from any further reclamation responsibility for the NOI.

No problems or violations were noted during this inspection.

Responses to this inspection report should be directed to Dustin Czapla at the Division of Reclamation, Mining and Safety, Grand Junction Field Office, 101 South 3rd Street, Room 301, Grand Junction, Colorado 81501, phone number (970) 243-6299.

PHOTOGRAPHS







Inspection Contact Address

Jaime Stuever City of Leadville 800 Harrison Ave. Leadville, CO 80461