

MINERALS PROGRAM INSPECTION REPORT PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:		MINE/PROSPECTING ID#:	MINERAL:	COUNTY:	
Box Creek Placer Mine		M-2018-053	Gold	Lake	
INSPECTION TYPE:		INSPECTOR(S):	INSP. DATE:	INSP. TIME:	
Pre-operation Inspection		Dustin M. Czapla	October 24, 2018	12:00	
OPERATOR:		OPERATOR REPRESENTATIVE:	TYPE OF OPERATION:		
Titan Au, Inc.			112 - Hard Rock Regular Operation		
REASON FOR INSPECTION:		BOND CALCULATION TYPE:	BOND AMOUNT:		
Pre-operation Inspection		None	No Bond Held		
DATE OF COMPLAINT:		POST INSP. CONTACTS:	JOINT INSP. AGENCY:		
NA		None	None		
WEATHER:	INSPECTOR'S SIGNATURE:		SIGNATURE DATE:		
Clear	2	h	October 31, 2018		

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS <u>Y</u>	(FN) FINANCIAL WARRANTY N	(RD) ROADS <u>N</u>
(HB) HYDROLOGIC BALANCE <u>N</u>	(BG) BACKFILL & GRADING <u>N</u>	(EX) EXPLOSIVES <u>N</u>
(PW) PROCESSING WASTE/TAILING N	(SF) PROCESSING FACILITIES N	(TS) TOPSOIL <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- N	(FW) FISH & WILDLIFE \underline{N}	(RV) REVEGETATION N
(SM) SIGNS AND MARKERS <u>N</u>	(SP) STORM WATER MGT PLAN N	(RS) RECL PLAN/COMP N
(ES) OVERBURDEN/DEV. WASTE <u>N</u>	(SC) EROSION/SEDIMENTATION N	(ST) STIPULATIONS <u>N</u>
(AT) ACID OR TOXIC MATERIALS N	(OD) OFF-SITE DAMAGE <u>N</u>	

 $Y = Inspected \ and \ found \ in \ compliance \ / \ N = Not \ inspected \ / \ NA = Not \ applicable \ to \ this \ operation \ / \ PB = Problem \ cited \ / \ PV = Possible \ violation \ cited \ A = Not \ applicable \ to \ this \ operation \ / \ PB = Problem \ cited \ / \ PV = Possible \ violation \ cited \ A = Not \ applicable \ to \ this \ operation \ / \ PB = Problem \ cited \ / \ PV = Possible \ violation \ cited \ A = Not \ applicable \ to \ this \ operation \ / \ PB = Problem \ cited \ / \ PV = Possible \ violation \ cited \ A = Not \ applicable \ to \ this \ operation \ / \ PB = Problem \ cited \ / \ PV = Possible \ violation \ / \ PV = Possible \ V = Possible$

PERMIT #: M-2018-053 INSPECTOR'S INITIALS: DMC INSPECTION DATE: October 24, 2018

OBSERVATIONS

This was a pre-operation inspection. An incomplete 112 application was submitted to the Division on October 11, 2018. A notice of incomplete application was sent to the operator on October 25, 2018. A representative for the operator was not present. Photographs of the site are included with this report.

The Box Creek Placer Mine is located approximately 8.5 miles southwest of Leadville and can be accessed from CR24 and CR24a. The application proposes an affected area that includes 950 acres. Much of the proposed affected area has been previously mined by historic operations. Historic, un-reclaimed, dredge workings are located throughout the site. Undisturbed areas within the proposed affected area consist mostly of high-altitude sage brush habitat.

Man-made structures not described in the application were not noted. The site conditions observed appeared consistent with those detailed in the 112 application package.

No problems or violations were noted during this inspection.

Responses to this inspection report should be directed to Dustin Czapla at the Division of Reclamation, Mining and Safety, Grand Junction Field Office, 101 South 3rd Street, Room 301, Grand Junction, Colorado 81501, phone number (970) 243-6299.

PHOTOGRAPHS









Inspection Contact Address

Mindy Miller Titan Au, Inc. 1935 65th Avenue Greeley, CO 80634

<u>CC:</u>

Katie Todt Greg Lewicki and Associates 3375 W. Powers Circle Littleton, CO 80123