




**MINERALS PROGRAM INSPECTION REPORT**  
**PHONE: (303) 866-3567**

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

<b>MINE NAME:</b> Colorado Red Rose Stone Resource	<b>MINE/PROSPECTING ID#:</b> M-2013-068	<b>MINERAL:</b> Granite, granite gneiss	<b>COUNTY:</b> Larimer
<b>INSPECTION TYPE:</b> Monitoring	<b>INSPECTOR(S):</b> Jared L. Ebert	<b>INSP. DATE:</b> January 31, 2019	<b>INSP. TIME:</b> 11:30
<b>OPERATOR:</b> Colorado Rose Red Inc.	<b>OPERATOR REPRESENTATIVE:</b> Caleb Liesveld	<b>TYPE OF OPERATION:</b> 111 - Construction by Government Agency	
<b>REASON FOR INSPECTION:</b> Normal I&E Program	<b>BOND CALCULATION TYPE:</b> Partial Bond	<b>BOND AMOUNT:</b> \$7,500.00	
<b>DATE OF COMPLAINT:</b> NA	<b>POST INSP. CONTACTS:</b> None	<b>JOINT INSP. AGENCY:</b> None	
<b>WEATHER:</b> Clear	<b>INSPECTOR'S SIGNATURE:</b> 	<b>SIGNATURE DATE:</b> February 15, 2019	

**GENERAL INSPECTION TOPICS**

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>Y</u>
(PW) PROCESSING WASTE/TAILING---- <u>Y</u>	(SF) PROCESSING FACILITIES----- <u>NA</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>Y</u>	(RV) REVEGETATION---- <u>NA</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>NA</u>	(RS) RECL PLAN/COMP-- <u>NA</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>Y</u>	(SC) EROSION/SEDIMENTATION--- <u>Y</u>	(ST) STIPULATIONS----- <u>NA</u>
(AT) ACID OR TOXIC MATERIALS----- <u>NA</u>	(OD) OFF-SITE DAMAGE----- <u>Y</u>	

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

## **OBSERVATIONS**

This was a monitoring inspection of the Colorado Rose Red Stone site, Division of Reclamation, Mining and Safety (DRMS or Division) permit number M-2013-068. The site is operated by Colorado Rose Red, Inc. (CRR). I, Jared Ebert with DRMS conducted the inspection. Mr. Caleb Liesveld with CRR met me at the site during the inspection.

The Colorado Rose Red Stone site is a three acre 111c mining operation in Larimer County. The site was mined for granite and the approved post-mining land use is rangeland. The site was inactive at the time of the inspection. On December 10, 2018, CRR received approval of an amendment application for a 110c mining operation (permit number M-1978-332) that now encompasses this 111c operation. However, the amendment has not been issued at this time as CRR has yet to post the additionally required surety. Once the bond is posted for the amended 110c permit area, CRR may request release of this 111c permit.

### **Backfilling and Grading:**

A small highwall about 12 feet in height exists at the site with a small pit depression at the base of the highwall. Rocks and boulders are at various locations surrounding the small excavation.

### **Explosives:**

Blasting was not occurring at the time of this inspection.

### **Gen. Compliance With Mine Plan:**

The site was inactive at the time of the inspection. The excavated area is above the level of the roadway on the south side of the site.

## **PHOTOGRAPHS**



**Figure 1. From the southeast side of the excavation looking at the highwall.**



**Figure 2. From the west side of the excavation looking east.**

### **Inspection Contact Address**

Caleb Liesveld  
Colorado Rose Red Inc.  
148 Cheyenne Ct.  
Lyons, CO 80540