

1313 Sherman Street, Room 215, Denver, CO 80203 P 303.866.3567 F 303.832.8106 http://mining.state.co.us

PERMIT INFORMATION

Permit Number: C-1996-084	County: Las Animas			
Mine Name: Lorencito Canyon Mine	Operation Type: Surface			
Operator: New Elk Coal Company, LLC	Permit Status: Permanent Cessation			
Operator Address:	Ownership: Private			
Mr. Louis Head				
12250 Highway 12	Operator Representative Present:			
Weston, CO 81091				
	Nick Mason, Vince Massarotti			
Operator Representative Signature: (Field Issuance Only)				
THE CONTROL OF THE CO				

INSPECTION INFORMATION

Inspection Start Date: February 1 Inspection Start Time: 12:00	•	Inspection Reason: N	al Complete Inspection Normal I&E Program	
Inspection End Date: February 21, 2019 Inspection End Time: 10:00		Weather: Clear		
Joint Inspection Agency:		Joint Inspection Contacts:		
None				
Post Inspection Agency:		Post Inspection Contacts:		
None				
Inspector(s):	Inspecto	r's Signature:	Signature Date:	
Robert D. Zuber, P.E.	Phot D. ZL			
			2/22/2019	

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

NA - Air Resource Protection Y - Roads

Y - Availability of Records R - Reclamation Success

NA - Backfill & Grading Y - Revegetation

R - Excess Spoil and Dev. Waste NA - Subsidence

NA - Explosives
Y - Slides and Other Damage
Y - Fish & Wildlife
NA - Support Facilities On-site

R - Hydrologic Balance Y - Signs and Markers

Y - Gen. Compliance With Mine Plan
 Y - Support Facilities Not On-site
 Y - Special Categories Of Mining

NA - Processing Waste Y - Topsoil

COMMENTS

A partial inspection was conducted by Rob Zuber of DRMS on February 20 and 21, 2019. Only the records check was done on the 20th. The weather was clear and cold. The ground contained snow on the north facing slopes but none on south facing slopes. Nick Mason and Vince Massarotti of NECC were present for the inspection.

Newer quarterly reports were not available; this needs to be rectified by NECC.

EXCESS SPOIL and DEVELOPMENT WASTE - Rule 4.09

Placement; Drainage Control; Surface Stabilization:

Fills 7, 8, and 9 were inspected. No large rills or gullies were seen.

HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

The following ponds were inspected: 5, 6, 8, 9 and 9A. The ponds on the south side (6 and 9a) as well as Pond 9 on the north side contained some water and ice from melted snow. Ponds 6 and 8 were dry. None of them were discharging. No problems were identified with embankments, spillways, or other features of the ponds.

No problems were found with ditches. In particular, the following ditches (at least significant segments of them) were inspected: D5, D8, D15, D71, and D86. Also, the ditches on sides of the fills were viewed closely, albeit from afar, and found to be stable.

RECLAMATION SUCCESS - Rule 4.15, Rule 3:

No erosion or other problems were seen with BA-3 (it was viewed from across the creek).

The hill known as "the knob" looked to be stable, with no gullies. However, rills on the west side should be addressed this winter, prior to spring 2019 runoff.

As noted in the past, there are many rills on the hillside above Pond 6 and on the hillside above the pond cleaning dump area. Vince Massarotti indicated that NECC staff would address these areas soon by placing branches in the rills. NECC should consider placing branches on the hill west of the bowl above ditch D9.

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

PHOTOGRAPHS



Pond 5 embankment



Fill 8



Ditch D84



Ditch D86



West side of "the knob"



Looking west at "the bowl" above Ditch D9



Pond 6 and area above it



Ditch D71



Fill 7



Fill 9 and Ditch D92

AVAILABILITY OF RECORDS

PERMIT RECORDS DRMS Permit	Expires 11/7/2022	HYDROLOGIC RECORDS NPDES Permit	CO0048988, Expires 12/31/2020
Permit Application w/Revisions	yes	NPDES Records	Q3 2015 (terminated monitoring)
Findings Document	RN4 (Jan. 2018)	Stormwater Management Plan	yes
Insurance Certificate	Exp. April 2019	SPCC Plan	n/a
Bond Document	\$927,121.00	MSHA Pond Inspections	n/a
Phased Bond Release	SL2,		
Documents/Findings	Findings 4/29/08	State Engineer's Pond Inspection	n/a
Air Emission Permits	Terminated	Quarterly Pond Inspections	* Comment 1
County Special Use Permits	SUP-01-020	Annual Hydrology Reports	Terminated
UG Mining Landowner Notification	n/a	 Ground Water Monitoring 	
Subsidence Monitoring Reports	n/a	 Surface Water Monitoring 	
Subsidence Monitoring Data	n/a	 Spring & Seep Monitoring 	
Rill & Gully Survey	2017 ARR	 Mine Water Discharge Monitoring 	
Vegetation Monitoring Data		 Mine Inflow Study 	
Specific Variance Approvals	n/a	 Water Consumption Records 	
Annual Reclamation Reports	2017	Well Permits	201451, 201453- 201476
Midterm Review Documents	MT4 (findings Jan. 2016)		
DRMS/OSM Inspection	Through		
Reports/Enforcement Actions	January 2019	BLASTING RECORDS	
Transfers/Succession of Operator	Executed 2008	Blasting Publication	n/a
Temporary Cessation Notification	n/a	Blasting Records (3 years)	n/a
Reclamation Cost Estimate	RN4, \$877,328	ATFE Explosives Permit	n/a
CERTIFICATIONS		Blasting Variances	n/a
Pond Certifications	Yes, Exhibit 15	Pre-Blast Surveys	n/a
Annual Certifications for Impoundments	n/a		
Fill Certifications for Excess Spoil or Underground Development Waste	2003	ADDITIONAL RECORDS (specify)	
 Quarterly Inspections 	Q3 2018	None at this time	
Compaction Testing	n/a		
Final Certification	n/a		
Coal Processing Waste Banks	n/a		
Haul Road Certifications	yes		
Access Road Certifications	yes		

Comments

*1 Through Q2 2018. Staff to contact Ron Thompson for newer reports.