

MINERALS PROGRAM INSPECTION REPORT PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:		MINE/PROSPECTING ID#:	MINERAL:	COUNTY:		
Blue Streak Mine		P-2007-057	Uranium and vanadit Montrose			
INSPECTION TYPE:		INSPECTOR(S):	INSP. DATE:	INSP. TIME:		
Monitoring		Dustin M. Czapla	April 17, 2019	12:30		
OPERATOR:		OPERATOR REPRESENTATIVE:	TYPE OF OPERATION:			
Nuvemco, LLC		Craig Howell	MP - Mineral Prospecting			
REASON FOR INSPECTION:		BOND CALCULATION TYPE:	BOND AMOUNT:			
Normal I&e Program		Complete Bond	\$21,862.00			
DATE OF COMPLAINT:		POST INSP. CONTACTS:	JOINT INSP. AGENCY:			
NA		None	None			
WEATHER:	INSPECTOR'S SIGNATURE:		SIGNATURE DATE:			
Clear	Dr.		April 18, 2019			

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS <u>Y</u>	(FN) FINANCIAL WARRANTY <u>Y</u>	(RD) ROADS <u>N</u>
(HB) HYDROLOGIC BALANCE <u>Y</u>	(BG) BACKFILL & GRADING \underline{Y}	(EX) EXPLOSIVES <u>N</u>
(PW) PROCESSING WASTE/TAILING N	(SF) PROCESSING FACILITIES \underline{N}	(TS) TOPSOIL <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- Y	(FW) FISH & WILDLIFE \underline{N}	(RV) REVEGETATION N
(SM) SIGNS AND MARKERS <u>Y</u>	(SP) STORM WATER MGT PLAN N	(RS) RECL PLAN/COMP N
(ES) OVERBURDEN/DEV. WASTE N	(SC) EROSION/SEDIMENTATION \underline{Y}	(ST) STIPULATIONS <u>N</u>
(AT) ACID OR TOXIC MATERIALS N	(OD) OFF-SITE DAMAGE <u>N</u>	

 $Y = Inspected \ and \ found \ in \ compliance \ / \ N = Not \ inspected \ / \ NA = Not \ applicable \ to \ this \ operation \ / \ PB = Problem \ cited \ / \ PV = Possible \ violation \ cited \ A = Not \ applicable \ to \ this \ operation \ / \ PB = Problem \ cited \ / \ PV = Possible \ violation \ violation \ violation \ / \ PV = Possible \ violation \ v$

PERMIT #: P-2007-057 INSPECTOR'S INITIALS: DMC INSPECTION DATE: April 17, 2019

OBSERVATIONS

This inspection was conducted as part of the Division of Reclamation, Mining and Safety's (Division) normal monitoring program. Craig Howell, representing the Operator, was present during this inspection. Photographs are included with this report in order to illustrate some of the conditions observed.

The Blue Streak Mine is located approximately nine miles southeast of Bedrock and accessed from CR FF16. The NOI operation affects five acres. The Division currently holds a financial warranty amount of \$21,862.00 for this site. Mine identification signage was noted at the entrance to the site.

The affected area was marked by t-posts that were clearly visible and adequate to delineate the affected area boundary.

The culverts crossing the access road that have been problematic in the past were replaced several years ago and appear to be well maintained and functioning adequately. Build-up of sediment around or in the culverts, or excessive erosion was not noted.

Overall, site conditions are orderly. Stormwater controls appear well maintained. There is no equipment or fuels stored on site. The portal is secured with a locked gate.

No problems or violations were noted during this inspection.

Responses to this inspection report should be directed to Dustin Czapla at the Division of Reclamation, Mining and Safety, Grand Junction Field Office, 101 South 3rd Street, Room 301, Grand Junction, Colorado 81501, phone number (970) 243-6299.

Inspection Contact Address

Craig Howell Nuvemco, LLC PO Box 297 Naturita, CO 81422

PHOTOGRAPHS











