

MINERALS PROGRAM INSPECTION REPORT PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:	MINE/PROSPECTING ID#:	MINERAL:	COUNTY:
Last Chance #3 & #4	M-2008-012	Uranium and Vanadium	Montrose
INSPECTION TYPE:	INSPECTOR(S):	INSP. DATE:	INSP. TIME:
Monitoring	Dustin M. Czapla	April 17, 2019	11:30
OPERATOR:	OPERATOR REPRESENTATIVE:	TYPE OF OPERATION:	
Nuvemco, LLC	Craig Howell	112d-1 - Designated Mining Operation	

REASON FOR INSPECTION:	BOND CALCULATION TYPE:	BOND AMOUNT:
Normal I&E Program	Complete Bond	\$45,250.00
DATE OF COMPLAINT:	POST INSP. CONTACTS:	JOINT INSP. AGENCY:
NA	None	None
WEATHER:	INSPECTOR'S SIGNATURE:	SIGNATURE DATE:
Clear	De	April 23, 2019

The following inspection topics were identified as having Problems or Possible Violations. OPERATORS SHOULD READ THE FOLLOWING PAGES CAREFULLY IN ORDER TO ASSURE COMPLIANCE WITH THE TERMS OF THE PERMIT AND APPLICABLE RULES AND REGULATIONS. If a Possible Violation is indicated, you will be notified under separate cover as to when the Mined Land Reclamation Board will consider possible enforcement action.

INSPECTION TOPIC: Availability Of Records

PROBLEM: It appears the operation is in a prolonged period of non-production. Rule 1.13.5 states that if an Operator temporarily ceases production of the mining operation for 180 days or more, the Operator must file a Notice of Temporary Cessation, in writing, to the Division.

CORRECTIVE ACTIONS: The Division recommends the Operator file for Temporary Cessation. The start date of the initial 5 year Temporary Cessation period is retroactive to the last date the operation was active. If that date is more than 5 years ago, the operator is required ask the Board for a 5 year extension to the Temporary Cessation period (per rule 1.13.5 (3) and 1.13.8 (b) or begin reclamation. Alternatively, if the operation has been active, provide a detailed report to the Division documenting activities that have occurred at the site along with justification explaining why the operation should not be considered to be in Temporary Cessation.

CORRECTIVE ACTION DUE DATE: 6/24/19

PERMIT #: M-2008-012 INSPECTOR'S INITIALS: DMC INSPECTION DATE: April 17, 2019

OBSERVATIONS

This inspection was conducted as part of the Division of Reclamation, Mining and Safety's (Division) normal monitoring program. Craig Howell, representing the Operator, was present during this inspection. Photographs are included with this report in order to illustrate some of the conditions observed.

The Last Chance #3 and #4 mine is located approximately fourteen miles west of Naturita and accessed from CR DD216. The site is a 112d-1 operation that includes a total of 49.98 permitted acres. The Division currently holds a financial warranty amount of \$45,250.00 for this site. The Division has updated the reclamation cost estimate, based on current reclamation costs, and determined that the financial warranty is sufficient at this time. The reclamation cost estimate is included with this report.

Adequate mine identification signage was noted at the entrance to the site.

The affected area was marked by posts that were clearly visible and adequate to delineate the affected area boundary.

Underground mining operations have been inactive since 2010. Since the Division's last inspection, activity at the site has consisted of site maintenance and weed control, and underground sampling. The operation appears to be in a prolonged period of non-production. Rule 1.13.5 states that if an Operator temporarily ceases production of the mining operation for 180 days or more, the Operator must file a Notice of Temporary Cessation, in writing, to the Division. This has been noted as a problem on page one of this report.

The constructed stormwater controls appear effective. No erosion or sedimentation issues were noted.

The topsoil stockpile northwest of Pond 2 is in place and appears stable and protected from disturbance.

The mine portal is secured with a locked gate. Ventholes are secured with locking grates.

Overall, conditions at the site are orderly. No other problems or violations were noted during this inspection.

Responses to this inspection report should be directed to Dustin Czapla at the Division of Reclamation, Mining and Safety, Grand Junction Field Office, 101 South 3rd Street, Room 301, Grand Junction, Colorado 81501, phone number (970) 243-6299.

PHOTOGRAPHS













PERMIT #: M-2008-012 INSPECTOR'S INITIALS: DMC INSPECTION DATE: April 17, 2019

GENERAL INSPECTION TOPICS

The following list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each

(AR) RECORDS <u>PB</u>	(FN) FINANCIAL WARRANTY $\underline{\mathbf{Y}}$	(RD) ROADS <u>N</u>
(HB) HYDROLOGIC BALANCE <u>Y</u>	(BG) BACKFILL & GRADING <u>N</u>	(EX) EXPLOSIVES <u>N</u>
(PW) PROCESSING WASTE/TAILING N	(SF) PROCESSING FACILITIES N	(TS) TOPSOIL <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE N	(RV) REVEGETATION N
(SM) SIGNS AND MARKERS <u>Y</u>	(SP) STORM WATER MGT PLAN N	(RS) RECL PLAN/COMP N
(ES) OVERBURDEN/DEV. WASTE <u>N</u>	(SC) EROSION/SEDIMENTATION \underline{Y}	(ST) STIPULATIONS <u>N</u>
(AT) ACID OR TOXIC MATERIALS <u>N</u>	(OD) OFF-SITE DAMAGE <u>N</u>	

Inspection Contact Address

Craig Howell Nuvemco, LLC P.O. Box 297 Naturita, CO 81422

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited