

Ebert - DNR, Jared <jared.ebert@state.co.us>

BLM Inspection 04/26/2019 - Canyon Rim Stone LLC., Cherry Canyon Quarry

Sanderson, Amber <asanderson@blm.gov> To: Jared.ebert@state.co.us Fri, May 3, 2019 at 3:20 PM

Hi Jared,

Attached is the most recent BLM annual inspection report of the Cherry Canyon Quarry. Please let me know if you have any questions or concerns.

Thank you,

Amber Sanderson Geologist - Mining Law and Mineral Materials BLM Royal Gorge Field Office 3028 E. Main St. Cañon City, CO 81212 (719) 269-8750

2019 04 26 Canon Rim Inspection.pdf 1835K





The BLM has conducted an inspection of your operations, which concludes whether the documented operations on file with BLM are compliant or noncompliant. Any non-compliance issues are reported in the Additional Actions Necessary section of this inspection.

Operation Type :	Surface – continual	□ Surface – intermittent		Underground	
Date: Apr 26, 2019 Time: 12:43 Weather: Windy , Sunny		Operation Name: Canyon Rim Stone LLC. – Cherry Canyon Case Number: COC078876 CDRMS #: M-2006-053			
<u>A</u>	<u>Attendees</u>	General			
		Operation (s) are in compliance with documentation on file			
BLM: A. Sanderson & J. R	ambo	✓ Yes	□ No	□ N/A	
Operator(s): Contacted, bu	it not present.	Operation(s) and disturbance on-site coincide with the operations and access on file ☑ Yes □ No □ N/A			
Other(s): None					

Inspection Purpose:

□ Pre-Operations

 \square General \square Final

□ Trespass

□ Complaint

Inspection Items	Compliant	Non- Compliant	N/A			
1. Method of Operations						
Hardrock Quarry, Pit, Other						
a. Hardrock Quarry	\checkmark					
Operations Equipment	\checkmark					
Processing Equipment	\checkmark					
• Blasting			\checkmark			
Interim Benches	\checkmark					
• Final Benches						
Working Floor	\checkmark					
b. Pit			\checkmark			
Operations Equipment						
Processing Equipment						
• Slopes						
c. Other						
Operations Equipment						
Processing Equipment						
2. Site Conditions						
a. Material/Waste Rock Management	\checkmark					
b. Erosion & Stormwater Control	\checkmark					
c. Man-made Structures	\checkmark					
d. Weed Management	\checkmark					
e. Safety Hazards	\checkmark					
f. Interim Reclamation			\checkmark			

Inspection Items	Compliant	Non- Compliant	N/A			
3. Housekeeping						
a. Container Management	V					
b. Spills/Leaks Observed	V					
c. Hazardous Substances/POL Management						
d. General Housekeeping	V					
4. Access						
a. Road Management	\checkmark					
b. Berms			\checkmark			
c. Security	V					
d. Signage	\checkmark					
e. Surface Water Controls			\checkmark			
5. Quality Assurance/Quality Control						
a. Routine Site Conditions Monitoring			\checkmark			
b. Air, Water, Noise, Other Monitoring			\checkmark			
c. Monitoring Reporting			\checkmark			
d. Regulatory Submittals			\checkmark			
e. Other Agency/Entity Permits	\checkmark					
7. Final Reclamation			\checkmark			
a. Exploration/Sampling Location						
b. Access Roads/Trails						
c. Grading						
d. Revegetation						
e. Removal of Structures						
f. Free of Trash						

Additional Actions Necessary

Non-Compliance Issues to be addressed by Operator

3.c. Housekeeping – Hazardous Substance/POL Management: 55 gallon yellow drum located on the southern end of the solar powered generator needs to be re-labeled with the type of material (e.g. non-potable water, diesel, oil, etc.) which is stored. The label seems to have rubbed off due to weather. Ref. image 9.

Final Notes

General Comments:

- Intermittent production and material is sold from stockpiled pallets which are primarily located along the north/northwestern permit boundary
- Upon the next BLM inspection (following fiscal year), the 3.c. non-compliance item will be inspected to verify compliance.

Proprietary Information:

None

Date inspection shared with CDRMS: 05/01/2019

Date inspection shared with Operator: 05/01/2019

Images

Image 1-3:



Comment: Working floor with splitter in the background. Highwalls are between 1 to 5 feet high. Multiple interim benches are used as highwall height increases.

Image 4:



Comment: Eastern view from the 5' highwall





Comment: Hydra splitter rock wall for wind protection/visual barrier **Image 6:**



Comment: Storage of POLs and mining related equipment and tools; located east of the splitter

Image 7-9:



Comment: Working floor/processing - Water source/generator for the hydro splitter with secondary containment (sandstone slab) and solar powered generator. Image 9 – depicts the yellow 55 gallon drum (3.c. non-compliance item)

Image 10:



Comment: Portable generator contained in a steel drum and stored along the north/northeastern boundary.

Image 11-14:



Comment: Stockpiled pallets of mined material located along the north/northwestern boundaries