

MINERALS PROGRAM INSPECTION REPORT PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

| MINE NAME: | MINE/PROSPECTING ID#: | MINERAL: | COUNTY: |
|------------------------|--------------------------|---------------------------------------|-------------|
| Limestone Pit No. 10 | M-2011-036 | Limestone, clay and | Moffat |
| | | gravel | |
| INSPECTION TYPE: | INSPECTOR(S): | INSP. DATE: | INSP. TIME: |
| Monitoring | Amy C. Yeldell | June 11, 2019 | 10:45 |
| OPERATOR: | OPERATOR REPRESENTATIVE: | TYPE OF OPERATION: | |
| Moffat County | Tim Dilldine | 112c - Construction Regular Operation | |
| REASON FOR INSPECTION: | BOND CALCULATION TYPE: | BOND AMOUNT: | |
| Normal I&E Program | None | \$0.00 | |
| DATE OF COMPLAINT: | POST INSP. CONTACTS: | JOINT INSP. AGENCY: | |
| NA | None | None | |
| WEATHER: | INSPECTOR'S SIGNATURE: | SIGNATURE DATE: | |
| Clear | Amy Geldell | June 19, 2019 | |

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

| (AR) RECORDS <u>N</u> | (FN) FINANCIAL WARRANTY NA | (RD) ROADS <u>Y</u> |
|--|---|----------------------------|
| (HB) HYDROLOGIC BALANCE <u>Y</u> | (BG) BACKFILL & GRADING <u>Y</u> | (EX) EXPLOSIVES <u>NA</u> |
| (PW) PROCESSING WASTE/TAILING N | (SF) PROCESSING FACILITIES NA | (TS) TOPSOIL <u>Y</u> |
| (MP) GENL MINE PLAN COMPLIANCE- <u>Y</u> | (FW) FISH & WILDLIFE \underline{Y} | (RV) REVEGETATION <u>Y</u> |
| (SM) SIGNS AND MARKERS <u>Y</u> | (SP) STORM WATER MGT PLAN N | (RS) RECL PLAN/COMP Y |
| (ES) OVERBURDEN/DEV. WASTE N | (SC) EROSION/SEDIMENTATION $\underline{\mathbf{Y}}$ | (ST) STIPULATIONS <u>Y</u> |
| (AT) ACID OR TOXIC MATERIALS NA | (OD) OFF-SITE DAMAGE <u>NA</u> | |

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted as part of the Colorado Division of Reclamation, Mining and Safety normal monitoring program. The Limestone Pit No. 1 is a 112c permitted site located off of County Road 10, approximately 20 miles west of Maybell in Moffat County. Tim Dilldine represented Moffat County and accompanied Amy Yeldell of the Division on the inspection.

The mine identification sign and affected area boundary markers are in place and in compliance with Rule 3.1.12. Little to no additional disturbances has occurred since the previous inspections. The site was inactive at the time of the inspection. No equipment or fuel was observed on site. There are several large stockpiles of processed materials on site. All of which are stable with no erosion.

All excavated slopes are no steeper than 3H:1V with a stormwater berm at the base of the slope. The topsoil and overburden piles are clearly marked with signage to prevent accidental loss. The piles have excellent vegetative cover.

There is some minor riling and erosion however it is all contained on-site within stormwater BMP's. The erosion may result in additional sediment loading of ponds prior to stormwater events. Berms were employed around the disturbed areas to prevent run-on or run-off from the site. The Division recommends that armoring or regrading occur if/when equipment is in the area to prevent future further damage. Several stormwater BMP's were observed in addition to two hydrologic discharge monitoring gauges. The two sediment basins remain well vegetated.

This pit is operated by a government entity therefore no bond is required. No problems or violations were noted during this inspection.

Responses to this inspection report should be directed to: Amy Yeldell at the Division of Reclamation, Mining and Safety, 1313 Sherman St., Room 215, Denver, CO 80203. Direct contact can be made by phone at 303-866-3567 ext 8183 or via email at amy.yeldell@state.co.us

Inspection Contact Address

Dan Miller/ Linda DeRose Moffat County PO Box 667 Craig, CO 81626

Enclosure

EC:

Travis Marshall, Senior EPS, Grand Junction DRMS

PHOTOGRAPHS



