



TRI-STATE GENERATION AND TRANSMISSION ASSOCIATION, INC.

HEADQUARTERS: P.O. BOX 33695 DENVER, COLORADO 80233-0695 303-452-6111

June 27, 2019

Sent via email: janet.binns@co.state.us

Mrs. Janet Binns
Environmental Protection Specialist
Colorado Division of Reclamation, Mining and Safety
1313 Sherman Street, Room 215
Denver, CO 80203

**RE: New Horizon North Mine
Permit No. C-2010-089
2nd Quarter 2019 Impoundment Inspections**

Dear Mrs. Binns:

Elk Ridge Mining and Reclamation, LLC (Elk Ridge) operates the New Horizon North Mine. Tri-State Generation and Transmission Association, Inc. (Tri-State) is the parent company of Elk Ridge. The New Horizon North Mine operates under Colorado Division of Reclamation, Mining and Safety (CDRMS) Permit No. C-2010-089.

In accordance with Rule 4.05.9(17), Tri-State is submitting the enclosed quarterly impoundment inspection on behalf of Elk Ridge.

If you have any questions about the enclosed quarterly impoundment reports, please contact Tony Tennyson at (970) 825-1232 at your convenience.

Sincerely,

for

Dan Casiraro
Senior Manager
Environmental Services

DJC:TT:der

Enclosures

cc: Frank Ferris (via email)
Chris Gilbreath (via email)
Jason Storey (via email)
Tony Tennyson (via email)
G747-11.3(21)c-8

AN EQUAL OPPORTUNITY / AFFIRMATIVE ACTION EMPLOYER

A Touchstone Energy* Cooperative

CRAIG STATION
P.O. BOX 1307
CRAIG, CO 81626-1307
970-824-4411

ESCALANTE STATION
P.O. BOX 577
PREWITT, NM 87045
505-972-5200

NUCLA STATION
P.O. BOX 698
NUCLA, CO 81424-0698
970-864-7316

POND EXAMINATION FORM, 2nd QUARTER 2019

Mine: **New Horizon North Mine**

Owner's Rep.: **Frank Ferris, Mine Manager**

Pond Name: **Pond 001**

Pond Type: **Partly Incised**

NPDES Permit & Outfall #: **CO-850062**

CDRM & S #: **C-2010-089**

Date Examined: **2-April-2019**

Date Last Examined: **18-March-2019**

Location Description: **2.4 miles NW of Nucla**

Legal Location: **Sec 25 of T47N R16W**

Inspector's Name: **Frank Ferris**

Circle or Write appropriate Response

- | | | | | |
|-----|---|----------------|---------------|-----|
| 1. | Seepage (specify location, color, and approx. volume) _____ | Yes | No | N/A |
| 2. | Cracks or scarps on crest or slopes _____ | Yes | No | N/A |
| 3. | Sloughing or bulging on slopes _____ | Yes | No | N/A |
| 4. | Major erosion problems _____ | Yes | No | N/A |
| 5. | Surface movements in valley bottom or on hillside _____ | Yes | No | N/A |
| 6. | Water impounded against toe _____ | Yes | No | N/A |
| 7. | Clogging | | | |
| | a) Spillway channels and pipes _____ | Yes | No | N/A |
| | b) Decant system _____ | Yes | No | N/A |
| | c) Diversion Ditches _____ | Yes | No | N/A |
| 8. | Cracking or crushing of pipes | | | |
| | a) Spillway pipes _____ | Yes | No | N/A |
| | b) Decant system _____ | Yes | No | N/A |
| 9. | Trash racks clear and in place _____ | Yes | No | N/A |
| 10. | Monitoring instrumentation _____ | Yes | No | N/A |

Comments: **Water covers 5% of the pond bottom**

POND EXAMINATION FORM, 2nd QUARTER 2019

Mine: **New Horizon North Mine**
 Pond Name: **Pond 002**
 NPDES Permit & Outfall #: **CO-850062**
 Date Examined: **2-April-2019**
 Location Description: **2.6 miles NW of Nucla**

Owner's Rep.: **Frank Ferris, Mine Manager**
 Pond Type: **Embankment**
 CDRM & S #: **C-2010-089**
 Date Last Examined: **18-March-2019**
 Legal Location: **Sec 25 of T47N R16W**
 Inspector's Name: **Frank Ferris**

Circle or Write appropriate Response

- | | | | | |
|-----|---|----------------|---------------|-----|
| 1. | Seepage (specify location, color, and approx. volume) _____ | Yes | No | N/A |
| 2. | Cracks or scarps on crest or slopes _____ | Yes | No | N/A |
| 3. | Sloughing or bulging on slopes _____ | Yes | No | N/A |
| 4. | Major erosion problems _____ | Yes | No | N/A |
| 5. | Surface movements in valley bottom or on hillside _____ | Yes | No | N/A |
| 6. | Water impounded against toe _____ | Yes | No | N/A |
| 7. | Clogging | | | |
| | a) Spillway channels and pipes _____ | Yes | No | N/A |
| | b) Decant system _____ | Yes | No | N/A |
| | c) Diversion Ditches _____ | Yes | No | N/A |
| 8. | Cracking or crushing of pipes | | | |
| | a) Spillway pipes _____ | Yes | No | N/A |
| | b) Decant system _____ | Yes | No | N/A |
| 9. | Trash racks clear and in place _____ | Yes | No | N/A |
| 10. | Monitoring instrumentation _____ | Yes | No | N/A |

Comments: **Water covers less than 5% of the pond bottom**