

Notes:

11. We continued to remove material from the 1.9 acres stripped area shown on the map (brown) and stockpiled material processed in previous years..

12. The mine floor is kept graded and no other reclamation is required at this time.

19. The current bond is adequate to complete reclamation. It was reviewed on 9/21/18 by the Division.

21. No additional groundwater monitoring data collected from May 2018 to current. The permit calls for only 8 quarters of sampling and we have data for 44 quarters. There is not exposed ground water in the mine.

22. Please refer to the 2019 Annual Report Map for location of the areas of disturbance in the mine.