

Attachment 1



Photo 1.
Erosion Gully 1 as shown in DRMS
Inspection report, looking west. Photo taken
7/12/18.



Photo 2.
Erosion Gully 1 after repair, looking west.
Photo taken 11/14/18.



Photo 3.
Erosion Gully 1 and surrounding slope after
repair, looking north. Photo taken 11/14/18.



Photo 4.
Erosion Gully 2 as shown in DRMS
Inspection report, looking southwest. Photo
taken 7/12/18.



Photo 5.
Erosion Gully 2 after repair, looking
northwest. Photo taken 11/14/18.



Photo 6.
Erosion Gully 2 and surrounding slope after
repair, looking east from bottom of slope. Photo
taken 11/14/18.



Photo 7.
Open Borehole 1 as shown in
DRMS Inspection report, looking
northwest. Photo taken 7/12/18.



Photo 8.
Open Borehole 1 after safeguard
installed, looking west. Photo
taken 11/19/18.



Photo 9.
Open Borehole 2 as shown in
DRMS Inspection report, looking
west. Photo taken 7/12/18.



Photo 10.
Open Borehole 2 after safeguard
installed, looking north. Photo
taken 11/19/18.



Photo 11. (Above)
Stockpile as shown in DRMS Inspection report, looking north.
Photo taken 7/12/18.



Photo 12. (Above)
Stockpile (circled in red) as shown in DRMS Inspection report, looking east. Photo taken 7/12/18.



Photo 13.
Removed stockpile area, looking east. Photo taken 11/14/18.



Photo 14.
Removed stockpile area, looking east (Sangre de Cristo Tunnel entrance located to right side of photo). Photo taken 11/14/18.



Photo 15.
Updated signage. Photo taken 9/25/19.



Photo 16.
Waste rock in super-sack. Photo taken 8/28/19.



Photo 16.
Waste rock removed. Photo taken 9/17/19.