

Cazier - DNR, Tim <tim.cazier@state.co.us>

**HGM Spill PO Thickener** 

1 message

Justin Bills <Justin.Bills@newmont.com>

Thu, Nov 14, 2019 at 4:25 PM

To: "Cazier - DNR, Tim" <tim.cazier@state.co.us> Cc: Justin Raglin <Justin.Raglin@newmont.com>, Tim Leedy <Tim.Leedy@newmont.com>, "michaela.cunningham@state.co.us" <michaela.cunningham@state.co.us>, "Lennberg - DNR, Patrick"

<patrick.lennberg@state.co.us>, Elliott Russell - DNR <elliott.russell@state.co.us>

Tim,

Today, at approximately 2:30pm we had a spill of process ore thickener at the Mill. A power bump caused a communication error, resulting in a backflow of solution, overtopping a tank interior to the Mill, spilling approximately 200 gallons of process solution out of an overhead door. All solution remained over the mill liner. The impacted material was over-excavated and placed on the mill feed pile.

A formal 5-day notification will be provided to the division in accordance with Rule 8.

Please let me know if you have any questions

Thank you,



Justin Bills

Environmental Manager

**T** 719.689.4046 **M** 719.306.3388

justin.bills@newmontgoldcorp.com

Newmont Goldcorp

300 N Third Street

PO Box 191

Victor, CO 80860

Please consider the environment before printing this e-mail.