




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Corkle Pit	MINE/PROSPECTING ID#: M-1995-023	MINERAL: Sand and gravel	COUNTY: Jackson
INSPECTION TYPE: Monitoring	INSPECTOR(S): Peter Hays	INSP. DATE: November 5, 2019	INSP. TIME: 12:00
OPERATOR: Corkle Construction	OPERATOR REPRESENTATIVE: Harry Corkle	TYPE OF OPERATION: 110c - Construction Limited Impact	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: Partial Bond	BOND AMOUNT: \$20,900.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
WEATHER: Clear	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: November 21, 2019	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>Y</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

The Corkle Pit was inspected by Peter Hays with the Division of Reclamation, Mining and Safety (Division/DRMS) as part of the Division's monitoring inspection program. The inspection was conducted in conjunction with the surety release inspection for the adjoining Corkle Construction Pit #2. The site was previously inspected by the Division on June 24, 2016. Mr. Harry Corkle with Corkle Construction was present during the inspection.

The site is an 110c operation permitted for 9.90 acres. The site was inactive during the inspection and mostly covered with snow. The Operator stated the site was closed for the season. A processing plant was located in the southeast portion of the site. Product stockpiles were located on the pit floor. Mining excavation progressed to the southwest since the last inspection. The Operator stated the pit may be used as a road base only site if the Operator is able to open a new mining operation.

The approved post-mining land use for the site is rangeland. Stockpiles of topsoil and overburden were observed adjacent to the north and south permit boundaries. The stockpiles were stable and no erosion features were observed during the inspection. The Division holds a financial warranty in the amount of \$20,900.00, which appeared adequate to reclaim the current mining disturbance.

An entrance sign was posted and permit boundary markers were observed as required by Rule 3.1.12. No problems were noted during the inspection. No photographs were taken during the inspection.

If you need additional information or have any questions, please contact me at Division of Reclamation, Mining and Safety, 1313 Sherman Street, Room 215, Denver, CO 80203, by telephone at 303.866.3567 x 8124, or by email at peter.hays@state.co.us.

Inspection Contact Address

Mr. Hughie Corkle
Corkle Construction
P.O. Box 306
Walden, CO 80480

Ec: Jared Ebert, DRMS