

QUARTERLY POND INSPECTION REPORT

Operator:	McClane Canyon Mining LLC	Quarter:	Fourth 2019
Mine:	McClane Canyon Mine C-1980-004	Inspection Date:	15-Nov-19

Pond Identification

Location

Sediment				
Pond				

Status During Inspection:

Approximate Water Level

Sediment (% total storage)

Outflow (cfs)

Dry				
100%				
0				

Features

Problem

Yes/No

--	--	--	--	--

Erosional

Rills & Gulleys

Inadequate Vegetation

Outlet Channel Erosion

Burrows

Other

No				
No				
No				
No				
No				

Structural

Differential Settling

Cracks or Slides

Seepage

Other

No				
No				
No				
No				

Appurtenant Structures

Defective Spillways

Dewatering Devices Clogged

Faulty Gates, Etc.

Other

No				
No				
No				
No				


Additional Comments

Invert of primary spillway is at elevation 5457.00.
Invert of emergency spillway is at elevation 5462.00.
Pond bottom about 7' below primary spillway

Maintenance Required:

None

Name of Inspector: Jim Stover



J. E. Stover
Colorado P.E. 19230 Date