



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

PERMIT INFORMATION

Permit Number: C-2010-088 Mine Name: Fruita Loadout Operator: CAM-Colorado, LLC Operator Address: Ronald Hull 424 Lewis Hargett Circle Suite 250 Lexington, KY 40503	County: Mesa Operation Type: Loadout Permit Status: Temporary Cessation Ownership: Private
	Operator Representative Present: None
Operator Representative Signature: (Field Issuance Only) 	

INSPECTION INFORMATION

Inspection Start Date: March 12, 2020 Inspection Start Time: 15:35 Inspection End Date: March 12, 2020 Inspection End Time: 16:05		Inspection Type: Coal Complete Inspection Inspection Reason: Normal I&E Program Weather: Clear	
Joint Inspection Agency: None		Joint Inspection Contacts: None	
Post Inspection Agency: None		Post Inspection Contacts: None	
Inspector(s): Clayton Wein	Inspector's Signature: <i>Clayton Wein</i>		Signature Date: 3/18/2020

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

N - Air Resource Protection

R - Availability of Records

N - Backfill & Grading

N - Excess Spoil and Dev. Waste

N - Explosives

R - Fish & Wildlife

R - Hydrologic Balance

Y - Gen. Compliance With Mine Plan

N - Other

N - Processing Waste

N - Roads

N - Reclamation Success

N - Revegetation

N - Subsidence

N - Slides and Other Damage

N - Support Facilities On-site

R - Signs and Markers

N - Support Facilities Not On-site

N - Special Categories Of Mining

N - Topsoil

COMMENTS

This was a complete inspection of the Fruita Loadout conducted on March 12, 2020. The inspection was completed by Clayton Wein of the Division. The site is inactive; therefore, no company representative was present for the inspection. The weather was clear with a temperature of 64 degrees F. The ground conditions were dry.

There has been no activity at the mine site since the previous Division Inspection (Photos 1 and 2). The site has been inactive since the permit was issued to the permittee. No disturbances have been created at the site.

AVAILABILITY OF RECORDS – Rule 5.02.4(1):

The records for the Fruita Loadout are located at the office of J. E. Stover and Associates in Grand Junction, CO. The records were in good condition and up to date. Please see the Availability of Records Form attached to the end of this report for more details.

FISH and WILDLIFE – Rule 4.18:

During the inspection of the site, several tracks and droppings from deer were seen. Many birds were seen and heard along Reed Wash.

HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

At the time of the inspection Reed Wash was flowing (Photo 3). The level of the water was low, typical for this time of year. The site was stable and there were no erosional features identified.

SIGNS AND MARKERS – Rule 4.02:

The mine identification sign was displayed to the left of the entrance to the site (Photo 4). The signs were located in a position that had an unobstructed view from the entrance. The sign was in good condition. Information displayed on the sign was up to date and included the required information about the permit, the

Number of Partial Inspection this Fiscal Year: 0

Number of Complete Inspections this Fiscal Year: 3

permittee and the Division.

DOCUMENTS RECEIVED: None

OTHER (SPECIFY): None

Number of Partial Inspection this Fiscal Year: 0

Number of Complete Inspections this Fiscal Year: 3

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

Number of Partial Inspection this Fiscal Year: 0

Number of Complete Inspections this Fiscal Year: 3

PHOTOGRAPHS

Note: The red arrow in the photos indicated the direction of north.



Photo 1: The west-central portion of the permit area.



Photo 2: The east-central portion of the permit area.

Number of Partial Inspection this Fiscal Year: 0

Number of Complete Inspections this Fiscal Year: 3



Photo 3: Reed Wash located in the western portion of the permit area.



Photo 4: The permit identification sign.

Number of Partial Inspection this Fiscal Year: 0

Number of Complete Inspections this Fiscal Year: 3

AVAILABILITY OF RECORDS**PERMIT RECORDS**

DRMS Permit	RN-1
Permit Application w/Revisions	OK
Findings Document	RN-1
Insurance Certificate	OK
Bond Document	RN-1
Phased Bond Release	NA
Documents/Findings	
Air Emission Permits	Exp.
County Special Use Permits	NA
UG Mining Landowner Notification	NA
Subsidence Monitoring Reports	NA
Subsidence Monitoring Data	NA
Rill & Gully Survey	NA
Vegetation Monitoring Data	Baseline
Specific Variance Approvals	NA
Annual Reclamation Reports	2019
Midterm Review Documents	MT-1
DRMS/OSM Inspection	Laserfiche
Reports/Enforcement Actions (3 Years)	
Transfers/Succession of Operator	SO-2
Temporary Cessation Notification	2012
Reclamation Cost Estimate	RN=1
CERTIFICATIONS	
Pond Certifications	NA
Annual Certifications for Impoundments	
Fill Certifications for Excess Spoil or Underground Development Waste	NA
• Quarterly Inspections	NA
• Compaction Testing	NA
• Final Certification	NA
Coal Processing Waste Banks	NA
Haul Road Certifications	NA
Access Road Certifications	NA

HYDROLOGIC RECORDS

NPDES Permit	COR-900152
NPDES Records	NA
Stormwater Management Plan	Req. Term.
SPCC Plan	NA
MSHA Pond Inspections	NA
	NA
State Engineer's Pond Inspection	
Quarterly Pond Inspections	NA
Annual Hydrology Reports	2019
• Ground Water Monitoring	NA
• Surface Water Monitoring	NA
• Spring & Seep Monitoring	NA
• Mine Water Discharge Monitoring	NA
• Mine Inflow Study	NA
• Water Consumption Records	NA
Well Permits	NA

BLASTING RECORDS

Blasting Publication	NA
Blasting Records (3 years)	NA
ATFE Explosives Permit	NA
Blasting Variances	NA
Pre-Blast Surveys	NA

**ADDITIONAL RECORDS
(specify)**

COMMENTS:

Number of Partial Inspection this Fiscal Year: 0Number of Complete Inspections this Fiscal Year: 3