



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

1313 Sherman Street, Room 215
Denver, CO 80203

3 April 2020

Miranda Kawcak
Moffat County Mining, LLC
29515 Routt County Road #27
Oak Creek, CO 80467

RE: Yoast Mine Permit; C1994082
Sediment Pond Inspections DRMS Review 2019 Quarter 4

Dear Ms. Kawcak:

Thank you for your submittal of the pond report. The Colorado Division of Reclamation, Mining and Safety (The Division) has reviewed the above referenced report. The Report was received by the Division on 22 January 2020. Sediment pond inspections were conducted by Seneca Coal Company, Jason Herden on 23 and 24 October 2019. The report is in compliance with the applicable sections of Rule 4.05.9

The following ponds held water but were not discharging at the time of inspection:

Stock Tank 1	Pond 11	Pond 11A
Pond 12A	Pond 13	Pond 14

Sediment levels were acceptable. Ponds 10 and 12 were discharging at 7.2 gpm and 77.3 gpm respectively.

One maintenance item was noted during the inspection; corrosion at outlet culvert to Pond 10. DRMS notes the existence of a native spring below the toe of the dam at Pond 13. The spring did not appear to be impacting the dam at the time of inspection.

The Division has no concerns at this time.

Best Regards,

Robin Reilley, M.S. GISP
Environmental Protection Specialist II

