

Bowie No. 1 Mine PO Box 1488 Paonia, CO. 81428 (970)986-6236

April 8, 2020

Mr. Rob Zuber Department of Natural Resources Division of Reclamation, Mining and Safety 1313 Sherman Street, Room 215 Denver, CO. 80203

RE: Bowie Resources LLC
Bowie No. 1 Mine
DRMS Permit No. C-1981-038
Quarterly Pond Inspection Reports

Dear Mr. Zuber:

Find enclosed Bowie No. 1 Mine Pond inspection reports for the 1st quarter of 2020. If you have any questions or concerns regarding this submittal contact me at (970)986-6236.

Sincerely;

Basil R. Bear Mine Manager

Bowie Resources LLC						
Bowie #1 Mine						
Sedimentation Pond						
ocalmonador i ona						
Loadout Pond						
Quarter:	1					
Inspection Date:	30-Mar-20					
Inspected By:	brb					
5						
Primary Elevation:	5724.00					
Cleanout Elevation:	5721.00					
Approximate Water Elevatio		spection:		DRY		
Approximate Sediment Elev				5720.00	I	
Outflow (C.F.S.)				0.00		THE PARTY OF THE P

					,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
Features:		[PANOLISEE		Commen	ts	
Fills & Gullies on Embankme	ent		No			
Inadequate Vegetation			No			
Outlet Channel Erosion			No		,5,E,W.1,7,300000000000000000000000000000000000	
Burrows			No			
Other						manufacture of the state of the
Structural:						
Differential Settling			No			
Cracks or Slides			No			· · · · · · · · · · · · · · · · · · ·
Seepage			No			W. 100 P.
Other						
Appurtenant Structure	es					
Defective Spillway			No			
Dewatering Device Clogged			No			
Faulty Gates, Baffles, Pump	\$		No			
Other		Gat	te Closed			
Additional Comments						3777)
	······································					
					Some .	
					3	
					****/0H	

	DRY	
Approximate Sediment Elevation at Time of Inspection: Outflow (C.F.S.)		
	0.00	
······································	NO.	· ///
	Comments	
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
NO		
, , , , , , , , , , , , , , , , , , , ,	, , , , , , , , , , , , , , , , , , , ,	
No.		
· · · · · · · · · · · · · · · · · · ·		
No		
No		
No		
.		
		No.
		9 - 1
	***	<u>\$</u>
	<u> </u>	. 9
	****	.4
		*
		ŀ
	No	No

Dourio Doggunges III			····	
Bowie Resources LL0 Bowie #1 Mine	,			
Sedimentation Pond				
 WM WS-1 Pond				
AAIAI AA 2-1 LOHU				
Quarter:	1			
Inspection Date:	30-Mar-20			
Inspected By:	brb			
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
Primary Elevation:	7,064.50			
Cleanout Elevation:	7,064.50			
Approximate Water Elevat		pection:		DRY
Approximate Sediment Ele				7061.00'
Outflow (C.F.S.)				0.00
	THE PARTY OF THE P			
Features:		_		Comments
Fills & Gullies on Embankr	ment		No	
Inadequate Vegetation			No	
Outlet Channel Erosion			No	
Burrows			No	
Other			No	
Structural:				
Differential Settling			No	
Cracks or Slides			No	
Seepage		No		
Other				
Appurtenant Structur	res			1
Defective Spillway			No	
Dewatering Device Clogged			No	
Faulty Gates, Baffles, Pumps			No	12 28 m
Other			Gate Closed	
Additional Comments				
Additional Comments	5			
		· · · · · · · · · · · · · · · · · · ·		

Bowie Resources LLC		
Bowie #1 Mine		
Sedimentation Pond		
WM WS-2 Pond		
Overton		
Quarter: 1		
Inspection Date: 30-Mar-20		
Inspected By: brb		
Primary Elevation: 7095.80		
Cleanout Elevation: 7095.80		
Approximate Water Elevation at Time of Insp	ection:	DRY
Approximate Sediment Elevation at Time of I	nspection:	7091.00'
Outflow (C.F.S.)		0.00
Fasting	***************************************	
Features:		Comments
Fills & Gullies on Embankment	No No	The state of the s
Inadequate Vegetation Outlet Channel Erosion	No No	
Burrows	No No	
Other	No No	
Othor	I NO	
Structural:		
Differential Settling	No	
Cracks or Slides	No	
Seepage	NO	
Other		
Appurtenant Structures		
Defective Spillway	No	
Dewatering Device Clogged	No	
Faulty Gates, Baffles, Pumps	No	
Other	Gate Open	
A - Little L O		
Additional Comments		
	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	