



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

8 April 2020

Tonia Perkins
Trapper Mine, Inc.
P.O. Box 187
Craig, Colorado 81626

RE: Trapper Mining Inc., Permit; C1981010
Review: Sediment Pond Inspections 2020 Q1

Dear Ms. Perkins

The Colorado Division of Reclamation, Mining and Safety (The Division) has reviewed the above referenced report. The first quarter Sediment Pond Inspection report was received by the Division on 2 April 2020.

The report complies with applicable sections of Rule 4.05.9. The inspection took place on 18, and 23 March 2020.

Maintenance issues addressed comprised the dredging of Middle Flume #3 during quarter 4 of 2019. No maintenance issues were noted in the current report.

The following ponds were discharging at a rate of less than 1 cubic foot/second:

1. *No Name #2, 4, 5*
2. *Johnson # 6, 7R, 8R, 9R, and 10R*
3. *East Pyeatt #1, 2, 3*

The following ponds held water and where not discharging at the time of inspection:

<i>Far East Buzzard</i>	<i>Coyote</i>	<i>West Pyeatt #1</i>	<i>Oak #1 and #2</i>
<i>Middle Flume #1 & #3</i>	<i>East Middle Flume</i>	<i>East Flume</i>	<i>Ute</i>
<i>Horse</i>	<i>West Horse</i>	<i>Deal #1</i>	<i>Industrial Waste Pond</i>

DRMS notes that sediment stored is approaching upper limit at Horse Pond with 55%. Should you have any questions or concerns please let me know, I'm available.

Best Regards,

Robin Reilley, M.S. GISP
Environmental Protection Specialist

