


**PERMIT INFORMATION**

<b>Permit Number:</b> C-2009-087 <b>Mine Name:</b> Peabody Sage Creek Mine <b>Operator:</b> Peabody Sage Creek Mining, LLC <b>Operator Address:</b> Ms Mirdanda Kawcak 29515 Routt County Road 27 Oak Creek, CO 80467	<b>County:</b> Routt <b>Operation Type:</b> Underground <b>Permit Status:</b> Temporary Cessation <b>Ownership:</b> Private
	<b>Operator Representative Present:</b>  None
<b>Operator Representative Signature:</b> (Field Issuance Only)	

**INSPECTION INFORMATION**

<b>Inspection Start Date:</b> May 6, 2020 <b>Inspection Start Time:</b> 09:00 <b>Inspection End Date:</b> May 6, 2020 <b>Inspection End Time:</b> 09:05		<b>Inspection Type:</b> Coal Partial Inspection <b>Inspection Reason:</b> Normal I&E Program <b>Weather:</b> Clear	
<b>Joint Inspection Agency:</b>  None		<b>Joint Inspection Contacts:</b>	
<b>Post Inspection Agency:</b>  None		<b>Post Inspection Contacts:</b>	
<b>Inspector(s):</b>  Tabetha Lynch  Brock Bowles	<b>Inspector's Signature:</b> 		<b>Signature Date:</b>  5/12/2020

## Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

N - Air Resource Protection  
N - Availability of Records  
N - Backfill & Grading  
N - Excess Spoil and Dev. Waste  
N - Explosives  
N - Fish & Wildlife  
R - Hydrologic Balance  
R - Gen. Compliance With Mine Plan  
N - Other  
N - Processing Waste

Y - Roads  
N - Reclamation Success  
N - Revegetation  
N - Subsidence  
Y - Slides and Other Damage  
N - Support Facilities On-site  
N - Signs and Markers  
N - Support Facilities Not On-site  
N - Special Categories Of Mining  
Y - Topsoil

## COMMENTS

This was an aerial inspection of the Sage Creek Mine DRMS Permit No. C-2009-087, Photos were taken by Brock Bowles on 5/6 and photos were observed by Tabettha Lynch with the Colorado Division of Reclamation, Mining, and Safety (Division).

### HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

Ponds appear to be holding water and discharging. No large erosional features were notes from observation of the aerial photos.



### GENERAL MINE PLAN COMPLIANCE:

Portal area appears stable. Some activity appears to be occurring onsite, which was being used as a

staging area for the Foidel Creek mine stoker coal construction.



#### **DOCUMENTS RECEIVED**

#### **OTHER (SPECIFY)**

#### **ENFORCEMENT ACTIONS/COMPLIANCE**

No enforcement actions were initiated as a result of this inspection, nor are any pending.