


PERMIT INFORMATION

Permit Number: C-1992-081 Mine Name: Hayden Gulch Loadout Operator: Hayden Gulch Terminal, LLC Operator Address: Ms Miranda Kawcak P.O. Box 670 Hayden, CO 81639	County: Routt Operation Type: Loadout Permit Status: Active Ownership: Private Operator Representative Present: None
Operator Representative Signature: (Field Issuance Only)	

INSPECTION INFORMATION

Inspection Start Date: May 6, 2020 Inspection Start Time: 09:00 Inspection End Date: Inspection End Time:	Inspection Type: Coal Partial Inspection Inspection Reason: Normal I&E Program Weather: Clear	
Joint Inspection Agency: None	Joint Inspection Contacts:	
Post Inspection Agency: None	Post Inspection Contacts:	
Inspector(s): Tabetha Lynch Brock Bowles	Inspector's Signature: 	Signature Date: 5/12/20

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

N - Air Resource Protection
N - Availability of Records
N - Backfill & Grading
N - Excess Spoil and Dev. Waste
N - Explosives
N - Fish & Wildlife
Y - Hydrologic Balance
R - Gen. Compliance With Mine Plan
N - Other
N - Processing Waste

Y - Roads
N - Reclamation Success
N - Revegetation
N - Subsidence
N - Slides and Other Damage
N - Support Facilities On-site
N - Signs and Markers
N - Support Facilities Not On-site
N - Special Categories Of Mining
Y - Topsoil

COMMENTS

This was an aerial inspection of the Hayden Gulch Loadout; DRMS Permit No. C-1992-081, operated by Hayden Gulch Terminal, LLC. Photos were taken by Brock Bowles on 5/6 and photos were observed by Tabettha Lynch with the Colorado Division of Reclamation, Mining, and Safety (Division).

GENERAL MINE PLAN COMPLIANCE:

Ponds appear to be holding water but not discharging. Little dry creek is flowing and does not appear to be flooding. No erosional features were noted from the aerial photos.





Parking lot appears to be growing over in weeds. Rail across Hwy 40 is currently still present. It appears ballast has been removed from the North side of Hwy 40 and reclamation working is occurring.

DOCUMENTS RECEIVED

OTHER (SPECIFY)

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.