

PERMIT INFORMATION

Permit Number: C-1981-012 Mine Name: New Elk Mine Operator: New Elk Coal Company, LLC Operator Address: Mr Louis Head 12250 Highway 12 Weston, CO 81091	County: Las Animas Operation Type: Underground Permit Status: Active Ownership: Private Operator Representative Present: NA			
Operator Representative Signature: (Field Issuance Only)				

INSPECTION INFORMATION

Inspection Start Date: May 18, 2020 Inspection Start Time: 12:00 Inspection End Date: May 19, 2020 Inspection End Time: 18:30			Inspection Type: Aerial Inspection Inspection Reason: Normal I&E Program Weather: Clear	
Joint Inspection Agency:		Joint Inspection Contacts:		
None				
Post Inspection Agency:		Post Inspection Contacts:		
None				
Inspector(s):	Inspector's Signature: S		Signature Date:	
Daniel Cunningham	Dani	4 6	Juster	
Brock Bowles				

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

N - Air Resource Protection Y - Roads

N - Availability of Records N - Reclamation Success

N - Backfill & Grading
 N - Revegetation
 N - Excess Spoil and Dev. Waste
 N - Subsidence

N - Excess Spon and Bev. Waste
 N - Explosives
 N - Slides and Other Damage
 N - Fish & Wildlife
 Y - Support Facilities On-site

Y - Hydrologic Balance N - Signs and Markers

N - Gen. Compliance With Mine Plan
 N - Support Facilities Not On-site
 Y - Special Categories Of Mining

Y - Processing Waste N - Topsoil

COMMENTS

The New Elk site was photographed from an airplane by Brock Bowles of DRMS on May 18, 2020. These photos were reviewed by Daniel Cunnigham of DRMS on May 19, 2020. The weather was clear.

HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

Ponds 001A, 004A, 006A, 007A, and 008A were inspected. Ponds 001A and 007A were observed with significant amount of water. No problems were noted with embankments or spill ways.

PROCESSING WASTE/COAL MINE WASTE PILES – Rule 4.10 and 4.11

Drainage Control; Surface Stabilization; Placement:

The RDA, Developmental Waste Pile and DWDA 2 appeared stable with no significant rills or erosion noted. The erosional issues noted in previous inspection of the RDA appear to have been stabilized.

ROADS - Rule 4.03

Construction 4.03.1(3)/4.03.2(3), Drainage 4.03.1(4)/4.03.2(4), Surfacing and Maintenance 4.03.1(5) and (6)/4.03.2(5) and (6), Reclamation 4.03.1(7)/4.03.2(7):

No issues were noted with roads on the permitted site.

SUPPORT FACILITIES - Rule 4.04:

No issues were noted with any support structure.

SPECIAL CATEGORIES OF MINING – Rules 4.22 through 4.27:

The Alluvial Valley Floor (AVF) along the Purgatoire River could be seen from the aerial photographs. There was no sign of damage to the river or any indication of impact to the AVF.

DOCUMENTS RECEIVED

OTHER (SPECIFY)

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.





Photo 1: Pond 004A



Photo 2: Support Facilities



Photo 3: RDA



Photo 4: Developmental Waste Pile