




**MINERALS PROGRAM INSPECTION REPORT**  
**PHONE: (303) 866-3567**

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

<b>MINE NAME:</b> Mooney Hills Permit	<b>MINE/PROSPECTING ID#:</b> M-2007-007	<b>MINERAL:</b> Aggregate	<b>COUNTY:</b> Las Animas
<b>INSPECTION TYPE:</b> Monitoring	<b>INSPECTOR(S):</b> Daniel Cunningham	<b>INSP. DATE:</b> May 14, 2020	<b>INSP. TIME:</b> 11:00
<b>OPERATOR:</b> All-Rite Paving & Redi-Mix, Inc.	<b>OPERATOR REPRESENTATIVE:</b> Phil Crumb	<b>TYPE OF OPERATION:</b> 110c - Construction Limited Impact	
<b>REASON FOR INSPECTION:</b> Normal I&E Program	<b>BOND CALCULATION TYPE:</b> Complete Bond	<b>BOND AMOUNT:</b> \$23,800.00	
<b>DATE OF COMPLAINT:</b> NA	<b>POST INSP. CONTACTS:</b> None	<b>JOINT INSP. AGENCY:</b> None	
<b>WEATHER:</b> Clear	<b>INSPECTOR'S SIGNATURE:</b> 	<b>SIGNATURE DATE:</b> June 4, 2020	

**GENERAL INSPECTION TOPICS**

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>NA</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>NA</u>
(PW) PROCESSING WASTE/TAILING---- <u>NA</u>	(SF) PROCESSING FACILITIES----- <u>NA</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>Y</u>	(RV) REVEGETATION---- <u>Y</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>NA</u>	(RS) RECL PLAN/COMP-- <u>NA</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>Y</u>	(SC) EROSION/SEDIMENTATION--- <u>NA</u>	(ST) STIPULATIONS----- <u>NA</u>
(AT) ACID OR TOXIC MATERIALS----- <u>NA</u>	(OD) OFF-SITE DAMAGE----- <u>NA</u>	

**Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited**

### **OBSERVATIONS**

This was a routine monitoring inspection conducted at the Mooney Hills Permit by DRMS representatives DJ Cunningham. Mr. Phil Crumb of All-Rite Paving & Redi-Mix attended the inspection. This site is an active, 9.9 acre, 110c permit held by All-Rite Paving & Redi-Mix. Mining activity was not taking place at the time of the inspection.

The site identification sign was posted and permit markers were observed to be in place throughout the entire operation, although several of them had been knocked over and need to be reset. Representative photos of the site identification sign and the disturbed area are also included with this report. All activity appeared to be in compliance with the approved mining plan. Topsoil was stored around the edge of the permit and was stable and well vegetated. No issues requiring corrective action were observed during this inspection.

The Division currently holds a corporate surety in the amount of \$23,800.00. Based on the observations made during this inspection, the Division estimates the reclamation liability at the site to be \$25,724.00. Enclosed is a copy of the Division's reclamation cost estimate. The Division requests that the Operator review the enclosed cost estimate and forward any questions or concerns to DRMS staff by June 2, 2020. The Division may issue a surety increase after June 2, 2020. If so, the Operator will have sixty days from the date of the surety increase notice to submit the required surety increase in accordance with Rule 4.2.1(2).

## PHOTOGRAPHS



Photo 1: Entrance Sign



Photo 2: Stock Pile



Photo 3: Topsoil Berm around Perimeter

**Inspection Contact Address**

Jodi Schreiber  
All-Rite Paving & Redi-Mix, Inc.  
P.O. Box 165  
Canon City, CO 81215

Enclosure: DRMS Bond Calculation

CC: