




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Rincon Materials	MINE/PROSPECTING ID#: M-2020-018	MINERAL: Sand and gravel	COUNTY: Eagle
INSPECTION TYPE: Preoperation Inspection	INSPECTOR(S): Stephanie Mitchell	INSP. DATE: May 18, 2020	INSP. TIME: 11:00
OPERATOR: Rincon Partners LLC	OPERATOR REPRESENTATIVE: Mike Young	TYPE OF OPERATION: 112c - Construction Regular Operation	
REASON FOR INSPECTION: Preoperation Inspection	BOND CALCULATION TYPE: Complete Bond	BOND AMOUNT: No Bond Held	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
WEATHER: Clear	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: June 23, 2020	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>N</u>	(BG) BACKFILL & GRADING----- <u>N</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>Y</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>N</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This was a pre-operation inspection conducted by the Division of Reclamation, Mining and Safety (Division) in response to the Construction Material Regular 112 Operation Reclamation permit application submitted by Rincon Partners, LLC. Mike Young, representing the applicant, was present during the inspection.

Photographs taken at the site during this inspection are included at the end of this report.

The Rincon Materials Pit is located 1 mile east of Dotsero in Eagle County and will be accessed from State HWY 6.

The appropriate public notice sign was in place.

The current site use is Rangeland, which will also be the post mining land use. The permit area will include 107.6 acres, of which 69.5 acres are expected to be mined. The unmined acreage will serve as buffer zones and topsoil/overburden stockpile area. It is expected that sufficient quantities of overburden material will be available on site for reclamation, and that enough topsoil will be salvaged in order to be distributed over the disturbed areas during reclamation at a depth of no less than 3 inches. The mined aggregate materials will be processed on site. The mine plan does not plan on encountering groundwater. The disturbance will be 10 acres at a time with contemporaneous reclamation.

Mining will move from the south to north in direction.

This inspection confirmed that the site conditions were accurately portrayed in the application package submitted by Rincon Materials, LLC.

The Division has calculated an adequate financial warranty estimate (enclosed) for this site.

Responses to this inspection report should be directed to Stephanie Mitchell at the Division of Reclamation, Mining and Safety, Grand Junction Field Office, 101 South 3rd Street, Room 301, Grand Junction, Colorado 81501, phone number (970) 242-5025.

PHOTOGRAPHS





Inspection Contact Address

Mike Young
Rincon Partners LLC
PO Box 480
Edwards, Co 81632

Enclosure: Bond Calculation