

PERMIT INFORMATION

Permit Number: C-1992-081 Mine Name: Hayden Gulch Loadout Operator: Hayden Gulch Terminal, LLC Operator Address: Ms Miranda Kawcak P.O. Box 670 Hayden, CO 81639	County: Routt Operation Type: Loadout Permit Status: Active Ownership: Private Operator Representative Present: none
Operator Representative Signature: (Field Issuance Only)	

INSPECTION INFORMATION

Inspection Start Date: July 6, 2020 Inspection Start Time: 09:00 Inspection End Date: July 6, 2020 Inspection End Time: 09:15		Inspection Type: Aerial Inspection Inspection Reason: Normal I&E Program Weather: Clear	
Joint Inspection Agency: None		Joint Inspection Contacts:	
Post Inspection Agency: None		Post Inspection Contacts:	
Inspector(s): Tabetha Lynch Brock Bowles	Inspector's Signature: 		Signature Date: 7/9/20

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

Y - Air Resource Protection
N - Availability of Records
Y - Backfill & Grading
N - Excess Spoil and Dev. Waste
N - Explosives
N - Fish & Wildlife
R - Hydrologic Balance
R - Gen. Compliance With Mine Plan
N - Other
N - Processing Waste

Y - Roads
Y - Reclamation Success
N - Revegetation
N - Subsidence
N - Slides and Other Damage
N - Support Facilities On-site
N - Signs and Markers
N - Support Facilities Not On-site
N - Special Categories Of Mining
Y - Topsoil

COMMENTS

This was an aerial inspection of the Hayden Gulch Loadout; DRMS Permit No. C-1992-081, operated by Hayden Gulch Terminal, LLC. Photos were taken by Brock Bowles on 7/9 and the report was written by Tabettha Lynch with the Colorado Division of Reclamation, Mining, and Safety (Division) on 7/9. No issues were noted as a result of this inspection.

HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

Ponds appear mostly dry and not discharging. Dry Creek appears to have lower flow. Culverts appear to be functional.



GENERAL MINE PLAN COMPLIANCE:

Tracks across Hwy 40 are in place. It does not appear any equipment is on site. Hay field on north side of Hwy 40 still has some flooding.



DOCUMENTS RECEIVED

OTHER (SPECIFY)

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.