



TRAPPER MINING INC.

June 29, 2020

Ms. Robin Reilley
Environmental Protection Specialist
Colorado Division of Reclamation, Mining, and Safety
1313 Sherman Street, Room 215
Denver, CO 80203

Dear Ms. Robin Reilley:

**RE: Trapper Mining Inc., Permit C-81-010
Second Quarter 2020 Sediment Pond Inspections**

All impoundment inspections were conducted by a qualified impoundment inspector. Inspections took place on May 19th, May 21st, May 27th, May 28th, June 1st, June 9th and June 10th of 2020.

There were four maintenance items:


- Far East Buzzard Pond #1's identification sign needs to be replaced.
(Replaced on June 9, 2020)
- Middle Flume Pond #3's sediment marker needs to be replaced.
- East Middle Flume Pond #1's sediment marker needs to be replaced.
- East Flume Pond #1's sediment marker needs to be replaced.

Trapper will address these maintenance items in a timely matter.

Data related to pond capacity is attached. The last column on the table provides an estimate of the remaining capacity in each pond where remaining capacity is defined as the volume remaining after considering the estimated amount of sediment noted during the inspections.

Please contact me if you have any questions.

Sincerely,


Tonia Marie Perkins
CO PE 43864

C: F. Luke/EQ file 118.7



Trapper Mining Inc.
Second Quarter 2020
Impoundment Inspection - Pond Capacity Data

Pond ID	Princ. Spillway Stage (ft)	Total Capacity to PS stage (acre-feet)	60% Sediment Capacity (acre-feet)	60% Sediment Capacity Stage (ft)	Remaining Design Capacity (acre-feet)	Inspection Observation (% sediment)	Qtr. 2 Estimated Sediment (acre-feet)	Qtr. 2 Approximate Rem. Capacity (acre-feet)
Far East Buzzard	2.0	0.03	0.02	1.4	0.01	10.00	0.00	0.03
Coyote	30.5	75.1	45.06	26.7	30.04	0.00	0.00	75.10
No Name #2	8.5	8.47	5.08	6.0	3.39	45.00	3.81	4.66
No Name #4	14.5	8.23	4.94	11.7	3.29	10.00	0.82	7.41
No Name #5	6.0	1.03	0.62	4.7	0.41	20.00	0.21	0.82
Johnson #6	9.0	1.80	1.08	7.1	0.72	20.00	0.36	1.44
Johnson #7R	7.0	2.99	1.79	5.2	1.20	35.00	1.05	1.94
Johnson #8	7.0	3.58	2.15	4.6	1.43	35.00	1.25	2.33
Johnson #9	8.5	2.74	1.64	6.6	1.10	15.00	0.41	2.33
Johnson #10	9.0	6.09	3.65	7.0	2.44	25.00	1.52	4.57
West Pyeatt #1	9.0	2.76	1.66	7.0	1.10	45.00	1.24	1.52
West Pyeatt #2	10.0	1.89	1.13	7.3	0.76	40.00	0.76	1.13
Middle Pyeatt #1	10.0	1.40	0.84	8.1	0.56	30.00	0.42	0.98
Middle Pyeatt #2	10.0	1.26	0.76	8.4	0.50	10.00	0.13	1.13
Middle Pyeatt #3	10.0	5.70	3.42	7.9	2.28	30.00	1.71	3.99
East Pyeatt #1	8.0	0.99	0.59	6.5	0.40	40.00	0.40	0.59
East Pyeatt #2	8.0	4.15	2.49	6.1	1.66	45.00	1.87	2.28
East Pyeatt #3	8.0	1.51	0.91	6.8	0.60	40.00	0.60	0.91
Grouse #1	7.5	3.35	2.01	5.7	1.34	40.00	1.34	2.01
Grouse # 2	4.5	0.79	0.47	3.6	0.32	10.00	0.08	0.71
Sage #1	8.0	2.67	1.60	6.4	1.07	10.00	0.27	2.40
Sage #2	7.0	2.07	1.24	5.8	0.83	10.00	0.21	1.86
Oak #1	13.0	1.43	0.86	10.6	0.57	45.00	0.64	0.79
Oak #2	9.5	0.93	0.56	7.7	0.37	5.00	0.05	0.88

Trapper Mining Inc.
Second Quarter 2020
Impoundment Inspection - Pond Capacity Data

Pond ID	Princ. Spillway Stage (ft)	Total Capacity to PS stage (acre-feet)	60% Sediment Capacity (acre-feet)	60% Sediment Capacity Stage (ft)	Design Capacity (acre-feet)	Remaining Capacity (% sediment)	Inspection Observation	Qtr. 2 Estimated Sediment (acre-feet)	Qtr. 2 Approximate Rem. Capacity (acre-feet)
West Flume	10.0	2.35	1.41	7.8	0.94	0.00	0.00	0.00	2.35
Middle Flume #1	11.7	0.80	0.48	9.0	0.32	15.00	0.12	0.12	0.68
Middle Flume # 3	14.0	3.36	2.02	10.5	1.34	10.00	0.34	0.34	3.02
East Middle Flume	13.0	2.56	1.54	9.2	1.02	0.00	0.00	0.00	2.56
East Flume	11.3	1.18	0.71	8.5	0.47	15.00	0.18	0.18	1.00
Ute	7.0	1.72	1.03	5.2	0.69	45.00	0.77	0.77	0.95
Horse	13.3	6.20	3.72	10.3	2.48	55.00	3.41	3.41	2.79
West Horse	13.0	2.00	1.20	9.7	0.80	20.00	0.40	0.40	1.60
Deal #1	16.8	2.00	1.20	15.1	0.80	40.00	0.80	0.80	1.20
Deal #2	6.0	1.66	0.60	3.1	1.06	0.00	0.00	0.00	1.66
Deacon #1	14.5	9.00	3.48	7.5	5.52	0.00	0.00	0.00	9.00
Deacon #2	12.0	7.03	3.60	7.7	3.43	0.00	0.00	0.00	7.03
Jeffway #1	9.0	2.86	1.20	5.3	1.66	0.00	0.00	0.00	2.86
Impoundment H	9.5	4.82	2.89	4.9	1.93	5.00	0.24	0.24	4.58

TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia PerkinsSIGNATURE: Tonia PerkinsDRAINAGE: **FAR EAST BUZZARD**DATE OF INSPECTION: 6/1/2020

POND IDENTIFICATION	Far East Buzzard #1		
Approximate water level:	<u>dry</u>		
Sediment level (% total storage):	<u>10%</u>		
Outflow (cfs):	<u>0</u>		
Sediment marker (install or replace)	<u>In Place</u>		
Identification sign (install or replace)	<u>In Place</u>		
EROSIONAL:			
Rills and/or gullies on downstream face.	<u>no</u>		
Rills and/or gullies on upstream face.	<u>no</u>		
Inadequate vegetation.	<u>no</u>		
Outlet channel erosion.	<u>no</u>		
Burrows.	<u>minimal</u>		
Erosion of toe.	<u>no</u>		
Water impounded against downstream toe.	<u>no</u>		
Other.	<u>-</u>		
STRUCTURAL:			
Differential settling.	<u>no</u>		
Cracks, slides, or scarps.	<u>no</u>		
Seepage (specify location, color, value).	<u>no</u>		
Defective spillways.	<u>no</u>		
Other.	<u>-</u>		
APPURTENANT STRUCTURES:			
Defective spillways.	<u>no</u>		
Dewatering device clogged.	<u>no</u>		
Cracking or crushing of pipes.	<u>no</u>		
Other.	<u>-</u>		
COMMENTS:			

ReAttached ID sign, needs to be replaced.



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR:

Tonia Perkins

SIGNATURE:



DRAINAGE: COYOTE

DATE OF INSPECTION:

6/1/2020

POND IDENTIFICATION	Coyote #1
Approximate water level:	10 1/2
Sediment level (% total storage):	0
Outflow (cfs):	0
Sediment marker (install or replace)	N/A
Identification sign (install or replace)	In Place
EROSIONAL:	
Rills and/or gullies on downstream face.	no
Rills and/or gullies on upstream face.	no
Inadequate vegetation.	no
Outlet channel erosion.	no
Burrows.	no
Erosion of toe.	no
Water impounded against downstream toe.	no
Other.	-
STRUCTURAL:	
Differential settling.	no
Cracks, slides, or scarps.	no
Seepage (specify location, color, value).	no
Defective spillways.	no
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	no
Dewatering device clogged.	no
Cracking or crushing of pipes.	no
Other.	-
COMMENTS:	

Sediment level is measured by a fixed surveyed elevation of 6298.11 ft. (9/29/10).



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: TIM CUMMINSSIGNATURE: *Tim Cummins*DRAINAGE: **NO NAME**DATE OF INSPECTION: 5-21-20

POND IDENTIFICATION	No Name #2	No Name #4	No Name #5
Approximate water level:	100 %	100 %	100 %
Sediment level (% total storage):	45 %	10 %	20 %
Outflow (cfs):	2 ICFS	2 ICFS	2 ICFS
Sediment marker (install or replace)	IN PLACE	IN PLACE	IN PLACE
Identification sign (install or replace)	IN PLACE	IN PLACE	IN PLACE
EROSIONAL:			
Rills and/or gullies on downstream face.	NO	NO	NO
Rills and/or gullies on upstream face.	NO	NO	NO
Inadequate vegetation.	NO	NO	NO
Outlet channel erosion.	NO	NO	NO
Burrows.	NO	NO	NO
Erosion of toe.	NO	NO	NO
Water impounded against downstream toe.	NO	NO	NO
Other.	—	—	—
STRUCTURAL:			
Differential settling.	NO	NO	NO
Cracks, slides, or scarps.	NO	NO	NO
Seepage (specify location, color, value).	NO	NO	NO
Defective spillways.	NO	NO	NO
Other.	—	—	—
APPURTENANT STRUCTURES:			
Defective spillways.	NO	NO	NO
Dewatering device clogged.	NO	NO	NO
Cracking or crushing of pipes.	NO	NO	NO
Other.	—	—	—
COMMENTS:			

#2: use riser/siphon tube as sediment marker; siphon top = 66%, bottom = 50%.

#4: use riser/siphon tube as sediment marker; siphon top = 75%, bottom = 60%.

#5: 60% level = top of post - 4.5'.



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: MATT CASSIDY

DRAINAGE: JOHNSON GULCH

SIGNATURE: [Signature]
DATE OF INSPECTION: 5-27-2020

POND IDENTIFICATION	Johnson #6	Johnson #7R	Johnson #8R	Johnson #9R	Johnson #10R
Approximate water level:	100%	100%	100%	100%	100%
Sediment level (% total storage):	20%	35%	35%	15%	25%
Outflow (cfs):	1 CFS	1 CFS	1 CFS	1 CFS	1 CFS
Sediment marker (install or replace)	IN PLACE	UNDERWATER IN PLACE	UNDERWATER IN PLACE	UNDERWATER IN PLACE	UNDERWATER IN PLACE
Identification sign (install or replace)	IN PLACE	IN PLACE	IN PLACE	IN PLACE	IN PLACE
EROSIONAL:					
Rills and/or gullies on downstream face.	NO	NO	NO	NO	NO
Rills and/or gullies on upstream face.	NO	NO	NO	NO	NO
Inadequate vegetation.	NO	NO	NO	NO	NO
Outlet channel erosion.	NO	NO	NO	NO	NO
Burrows.	NO	NO	NO	NO	NO
Erosion of toe.	NO	NO	NO	NO	NO
Water impounded against downstream toe.	NO	NO	NO	NO	NO
Other.	—	—	—	—	—
STRUCTURAL:					
Differential settling.	NO	NO	NO	NO	NO
Cracks, slides, or scarps.	NO	NO	NO	NO	NO
Seepage (specify location, color, value).	NO	NO	NO	NO	NO
Defective spillways.	NO	NO	NO	NO	NO
Other.	—	—	—	—	—
APPURTENANT STRUCTURES:					
Defective spillways.	NO	NO	NO	NO	NO
Dewatering device clogged.	NO	NO	NO	NO	NO
Cracking or crushing of pipes.	NO	NO	NO	NO	NO
Other.	—	—	—	—	—
COMMENTS:					

#6: use riser/siphon tube as sediment marker; siphon top = 90%, top - 1.5' = 60%.



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Justin FednerSIGNATURE: JCFDRAINAGE: **WEST PYEATT**DATE OF INSPECTION: 5-21-2020

POND IDENTIFICATION	West Pyeatt #1	West Pyeatt #2
Approximate water level:	40% 45% 8	26 40% 8
Sediment level (% total storage):		
Outflow (cfs):		
Sediment marker (install or replace)	In Place	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	NO	NO
Rills and/or gullies on upstream face.	NO	NO
Inadequate vegetation.	NO	NO
Outlet channel erosion.	NO	NO
Burrows.	NO	NO
Erosion of toe.	NO	NO
Water impounded against downstream toe.	NO	NO
Other.	—	—
STRUCTURAL:		
Differential settling.	NO	NO
Cracks, slides, or scarps.	NO	NO
Seepage (specify location, color, value).	NO	NO
Defective spillways.	NO	NO
Other.	—	—
APPURTENANT STRUCTURES:		
Defective spillways.	NO	NO
Dewatering device clogged.	NO	NO
Cracking or crushing of pipes.	NA	NA
Other.	—	—
COMMENTS:		




TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Justin FedunSIGNATURE: [Signature]DRAINAGE: **MIDDLE PYEATT**DATE OF INSPECTION: 5-21-2020

POND IDENTIFICATION	Middle Pyeatt #1	Middle Pyeatt #2	Middle Pyeatt #3
Approximate water level:	Dry	Dry	Dry
Sediment level (% total storage):	30%	10%	30%
Outflow (cfs):	0	0	0
Sediment marker (install or replace)	In Place	In Place	In Place
Identification sign (install or replace)	In Place	In Place	In Place
EROSIONAL:			
Rills and/or gullies on downstream face.	NO	NO	NO
Rills and/or gullies on upstream face.	NO	NO	NO
Inadequate vegetation.	NO	NO	NO
Outlet channel erosion.	NO	NO	NO
Burrows.	NO	NO	NO
Erosion of toe.	NO	NO	NO
Water impounded against downstream toe.	NO	NO	NO
Other.	-	-	-
STRUCTURAL:			
Differential settling.	NO	NO	NO
Cracks, slides, or scarps.	NO	NO	NO
Seepage (specify location, color, value).	NO	NO	NO
Defective spillways.	NO	NO	NO
Other.	-	-	-
APPURTENANT STRUCTURES:			
Defective spillways.	NO	NO	NO
Dewatering device clogged.	NO	NO	NO
Cracking or crushing of pipes.	NA	NA	NA
Other.	-	-	-
COMMENTS:			



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: MATT CASSIDYSIGNATURE: DRAINAGE: EAST PYEATTDATE OF INSPECTION: 5-19-2020

POND IDENTIFICATION	East Pyeatt #1	East Pyeatt #2	East Pyeatt #3
Approximate water level:	100%	100%	100%
Sediment level (% total storage):	40%	45%	40%
Outflow (cfs):	1 CFS	1 CFS	1 CFS
Sediment marker (install or replace)	UNDER WATER	UNDER WATER	UNDER WATER
Identification sign (install or replace)	IN PLACE	IN PLACE	IN PLACE
EROSIONAL:			
Rills and/or gullies on downstream face.	NO	NO	NO
Rills and/or gullies on upstream face.	NO	NO	NO
Inadequate vegetation.	NO	NO	NO
Outlet channel erosion.	NO	NO	NO
Burrows.	NO	NO	NO
Erosion of toe.	NO	NO	NO
Water impounded against downstream toe.	NO	NO	NO
Other.	—	—	—
STRUCTURAL:			
Differential settling.	NO	NO	NO
Cracks, slides, or scarps.	NO	NO	NO
Seepage (specify location, color, value).	NO	NO	NO
Defective spillways.	NO	NO	NO
Other.	—	—	—
APPURTENANT STRUCTURES:			
Defective spillways.	NO	NO	NO
Dewatering device clogged.	NO	NO	NO
Cracking or crushing of pipes.	NO	NO	NO
Other.	—	—	—
COMMENTS:			



TRAPPER MINING INC.

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Monte McCoySIGNATURE: Monte McCoyDRAINAGE: **GROUSE GULCH**DATE OF INSPECTION: 6-1-2020

POND IDENTIFICATION	Grouse #1	Grouse #2
Approximate water level:	Dry	
Sediment level (% total storage):	40%	Dry
Outflow (cfs):	0	100%
Sediment marker (install or replace)	in place	in place
Identification sign (install or replace)	in place	in place
EROSIONAL:		
Rills and/or gullies on downstream face.	no	no
Rills and/or gullies on upstream face.	no	no
Inadequate vegetation.	no	no
Outlet channel erosion.	no	no
Burrows.	no	no
Erosion of toe.	no	no
Water impounded against downstream toe.	no	no
Other.	—	—
STRUCTURAL:		
Differential settling.	no	no
Cracks, slides, or scarps.	no	no
Seepage (specify location, color, value).	no	no
Defective spillways.	no	no
Other.	—	—
APPURTENANT STRUCTURES:		
Defective spillways.	no	no
Dewatering device clogged.	no	no
Cracking or crushing of pipes.	no	no
Other.	—	—
COMMENTS:		



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Mate McLeaySIGNATURE: Mate McLeayDRAINAGE: **SAGE GULCH**DATE OF INSPECTION: 6-1-2020

POND IDENTIFICATION	Sage #1	Sage #2
Approximate water level:	Dry	
Sediment level (% total storage):	10%	Dry
Outflow (cfs):	0	10%
Sediment marker (install or replace)	In Place	In Place
Identification sign (install or replace)	In Place	In Place
EROSIONAL:		
Rills and/or gullies on downstream face.	no	no
Rills and/or gullies on upstream face.	no	no
Inadequate vegetation.	no	no
Outlet channel erosion.	no	no
Burrows.	yes	yes
Erosion of toe.	yes no mm.	no
Water impounded against downstream toe.	no	no
Other.		
STRUCTURAL:		
Differential settling.	no	no
Cracks, slides, or scarps.	no	no
Seepage (specify location, color, value).	no	no
Defective spillways.	no	no
Other.		
APPURTENANT STRUCTURES:		
Defective spillways.	no	no
Dewatering device clogged.	no	no
Cracking or crushing of pipes.	no	no
Other.		

COMMENTS: Animal burrows present, not impacting structure of Dam.

TRAPPER MINING INC.**QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR:

Tonia Perkins

SIGNATURE:

*Donna Fisher*DRAINAGE: **OAK GULCH**

DATE OF INSPECTION:

6/1/2020

POND IDENTIFICATION	Oak #1	Oak #2
Approximate water level:	<i>55'</i>	<i>15'</i>
Sediment level (% total storage):	<i>45'</i>	<i>5'</i>
Outflow (cfs):	<i>0</i>	<i>0</i>
Sediment marker (install or replace)	<i>In Place</i>	<i>In Place</i>
Identification sign (install or replace)	<i>In Place</i>	<i>In Place</i>
EROSIONAL:		
Rills and/or gullies on downstream face.	<i>no</i>	<i>no</i>
Rills and/or gullies on upstream face.	<i>no</i>	<i>no</i>
Inadequate vegetation.	<i>no</i>	<i>no</i>
Outlet channel erosion.	<i>no</i>	<i>no</i>
Burrows.	<i>yes</i>	<i>no</i>
Erosion of toe.	<i>no</i>	<i>no</i>
Water impounded against downstream toe.	<i>no</i>	<i>no</i>
Other.	<i>-</i>	<i>-</i>
STRUCTURAL:		
Differential settling.	<i>no</i>	<i>no</i>
Cracks, slides, or scarps.	<i>no</i>	<i>no</i>
Seepage (specify location, color, value).	<i>no</i>	<i>no</i>
Defective spillways.	<i>no</i>	<i>no</i>
Other.	<i>-</i>	<i>-</i>
APPURTENANT STRUCTURES:		
Defective spillways.	<i>no</i>	<i>no</i>
Dewatering device clogged.	<i>no</i>	<i>no</i>
Cracking or crushing of pipes.	<i>no</i>	<i>no</i>
Other.	<i>-</i>	<i>-</i>
COMMENTS:		

OAK #1 - Some vegetation in outlet, disrupting water flow would be minimal.
OAK #2 - " " " " " "

OAK #1 - Some burrows on the east & north part of pond. They are not compromising the pond structure.



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Sean HorvorkaSIGNATURE: Sean HorvorkaDRAINAGE: **WEST FLUME**DATE OF INSPECTION: 8-5-28-20

POND IDENTIFICATION	West Flume #1		
Approximate water level:	<u>Ø Dry</u>		
Sediment level (% total storage):	<u>Ø Minimal</u>		
Outflow (cfs):	<u>Ø</u>		
Sediment marker (install or replace)	<u>In Place</u>		
Identification sign (install or replace)	<u>In Place</u>		
EROSIONAL:			
Rills and/or gullies on downstream face.	<u>No</u>		
Rills and/or gullies on upstream face.	<u>No</u>		
Inadequate vegetation.	<u>No</u>		
Outlet channel erosion.	<u>No</u>		
Burrows.	<u>No</u>		
Erosion of toe.	<u>No</u>		
Water impounded against downstream toe.	<u>No</u>		
Other.	<u>-</u>		
STRUCTURAL:			
Differential settling.	<u>No</u>		
Cracks, slides, or scarps.	<u>No</u>		
Seepage (specify location, color, value).	<u>No</u>		
Defective spillways.	<u>No</u>		
Other.	<u>-</u>		
APPURTENANT STRUCTURES:			
Defective spillways.	<u>No</u>		
Dewatering device clogged.	<u>No</u>		
Cracking or crushing of pipes.	<u>No</u>		
Other.	<u>-</u>		
COMMENTS:			

Pond Dry

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Sean HovackaSIGNATURE: Sean HovackaDRAINAGE: **MIDDLE FLUME**DATE OF INSPECTION: 5-28-20

POND IDENTIFICATION	Middle Flume #1	Middle Flume #3
Approximate water level:	30' 1/2	60' 1/2
Sediment level (% total storage):	15%	10%
Outflow (cfs):	0	0
Sediment marker (install or replace)	In Place	Replace
Identification sign (install or replace)	In Place	Replace Inspection Sign
EROSIONAL:		
Rills and/or gullies on downstream face.	No	No
Rills and/or gullies on upstream face.	No	No
Inadequate vegetation.	No	No
Outlet channel erosion.	No	No
Burrows.	No	No
Erosion of toe.	No	No
Water impounded against downstream toe.	No	No
Other.	No	-
STRUCTURAL:		
Differential settling.	No	No
Cracks, slides, or scarps.	No	No
Seepage (specify location, color, value).	No	No
Defective spillways.	No	No
Other.	-	-
APPURTENANT STRUCTURES:		
Defective spillways.	No	No
Dewatering device clogged.	No	No
Cracking or crushing of pipes.	No	No
Other.	-	-
COMMENTS:		



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Sean Horvacka

DRAINAGE: EAST MIDDLE FLUME

SIGNATURE: Sean Horvacka

DATE OF INSPECTION: 5-28-20

POND IDENTIFICATION	East Middle Flume #1
Approximate water level:	<u>40 ft.</u>
Sediment level (% total storage):	<u>Minimal</u>
Outflow (cfs):	<u>0</u>
Sediment marker (install or replace)	<u>Replace</u>
Identification sign (install or replace)	<u>In Place</u>
EROSIONAL:	
Rills and/or gullies on downstream face.	<u>No</u>
Rills and/or gullies on upstream face.	<u>No</u>
Inadequate vegetation.	<u>No</u>
Outlet channel erosion.	<u>No</u>
Burrows.	<u>No</u>
Erosion of toe.	<u>No</u>
Water impounded against downstream toe.	<u>No</u>
Other.	<u>-</u>
STRUCTURAL:	
Differential settling.	<u>No</u>
Cracks, slides, or scarps.	<u>No</u>
Seepage (specify location, color, value).	<u>No</u>
Defective spillways.	<u>No</u>
Other.	<u>-</u>
APPURTENANT STRUCTURES:	
Defective spillways.	<u>No</u>
Dewatering device clogged.	<u>No</u>
Cracking or crushing of pipes.	<u>No</u>
Other.	<u>-</u>
COMMENTS:	



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Sean HovorkaSIGNATURE: Sean HovorkaDRAINAGE: **EAST FLUME**DATE OF INSPECTION: 5-28-20

POND IDENTIFICATION	East Flume #1
Approximate water level:	15'
Sediment level (% total storage):	15% 1
Outflow (cfs):	0
Sediment marker (install or replace)	Replace
Identification sign (install or replace)	Install
EROSIONAL:	
Rills and/or gullies on downstream face.	No
Rills and/or gullies on upstream face.	No
Inadequate vegetation.	No
Outlet channel erosion.	No
Burrows.	No
Erosion of toe.	No
Water impounded against downstream toe.	No
Other.	-
STRUCTURAL:	
Differential settling.	No
Cracks, slides, or scarps.	No
Seepage (specify location, color, value).	No
Defective spillways.	No
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	No
Dewatering device clogged.	No
Cracking or crushing of pipes.	No
Other.	-
COMMENTS:	



TRAPPER MINING INC.

TRAPPER MINING INC.**QUARTERLY SEDIMENT POND INSPECTION REPORT**INSPECTOR: Tonia PerkinsSIGNATURE: *Tonia Perkins*DRAINAGE: **UTE GULCH**DATE OF INSPECTION: 6/1/2020

POND IDENTIFICATION	Ute #1		
Approximate water level:	70%		
Sediment level (% total storage):	45%		
Outflow (cfs):	0		
Sediment marker (install or replace)	In Place		
Identification sign (install or replace)	In Place		
EROSIONAL:			
Rills and/or gullies on downstream face.	no		
Rills and/or gullies on upstream face.	no		
Inadequate vegetation.	minimal		
Outlet channel erosion.	no		
Burrows.	no		
Erosion of toe.	no		
Water impounded against downstream toe.	no		
Other.	-		
STRUCTURAL:			
Differential settling.	no		
Cracks, slides, or scarps.	no		
Seepage (specify location, color, value).	no		
Defective spillways.	no		
Other.	-		
APPURTENANT STRUCTURES:			
Defective spillways.	no		
Dewatering device clogged.	no		
Cracking or crushing of pipes.	no		
Other.	-		
COMMENTS:			

Minimal vegetation by flume, not impacting waterflow.



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Graham RobertsSIGNATURE: *GR*DRAINAGE: **HORSE GULCH**DATE OF INSPECTION: 6-10-20

POND IDENTIFICATION	Horse #1			
Approximate water level:	80%			
Sediment level (% total storage):	55%			
Outflow (cfs):	0			
Sediment marker (install or replace)	In place			
Identification sign (install or replace)	In place			
EROSIONAL:				
Rills and/or gullies on downstream face.	No			
Rills and/or gullies on upstream face.	No			
Inadequate vegetation.	No			
Outlet channel erosion.	No			
Burrows.	No			
Erosion of toe.	No			
Water impounded against downstream toe.	No			
Other.	—			
STRUCTURAL:				
Differential settling.	No			
Cracks, slides, or scarps.	No			
Seepage (specify location, color, value).	No			
Defective spillways.	No			
Other.	—			
APPURTENANT STRUCTURES:				
Defective spillways.	No			
Dewatering device clogged.	NA			
Cracking or crushing of pipes.	NA			
Other.	—			
COMMENTS:				



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Graham RobertsSIGNATURE: *GR*DRAINAGE: **WEST HORSE GULCH**DATE OF INSPECTION: 6-10-20

POND IDENTIFICATION	West Horse #1		
Approximate water level:	0%		
Sediment level (% total storage):	20%		
Outflow (cfs):	0		
Sediment marker (install or replace)	In place		
Identification sign (install or replace)	In place		
EROSIONAL:			
Rills and/or gullies on downstream face.	No		
Rills and/or gullies on upstream face.	No		
Inadequate vegetation.	No		
Outlet channel erosion.	No		
Burrows.	No		
Erosion of toe.	No		
Water impounded against downstream toe.	No		
Other.	—		
STRUCTURAL:			
Differential settling.	No		
Cracks, slides, or scarps.	No		
Seepage (specify location, color, value).	No		
Defective spillways.	No		
Other.	—		
APPURTENANT STRUCTURES:			
Defective spillways.	No		
Dewatering device clogged.	NA		
Cracking or crushing of pipes.	NA		
Other.	—		
COMMENTS:			



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Graham RobertsSIGNATURE: *Sh Rh*DRAINAGE: **DEAL GULCH**DATE OF INSPECTION: 6-10-20

POND IDENTIFICATION	Deal #1	Deal #2
Approximate water level:	95%	0%
Sediment level (% total storage):	40%	0%
Outflow (cfs):	0	0
Sediment marker (install or replace)	In place	In place
Identification sign (install or replace)	In place	In place
EROSIONAL:		
Rills and/or gullies on downstream face.	No	No
Rills and/or gullies on upstream face.	No	No
Inadequate vegetation.	No	No
Outlet channel erosion.	No	No
Burrows.	No	No
Erosion of toe.	No	No
Water impounded against downstream toe.	No	No
Other.	—	—
STRUCTURAL:		
Differential settling.	No	No
Cracks, slides, or scarps.	No	No
Seepage (specify location, color, value).	No	No
Defective spillways.	No	No
Other.	—	—
APPURTENANT STRUCTURES:		
Defective spillways.	No	No
Dewatering device clogged.	NA	NA
Cracking or crushing of pipes.	NA	NA
Other.	—	—
COMMENTS:		



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Graham RobertsSIGNATURE: Lh. RobertsDRAINAGE: **DEACON**DATE OF INSPECTION: 6-9-20

POND IDENTIFICATION	Deacon #1	Deacon #2
Approximate water level:	0	0
Sediment level (% total storage):	0	0
Outflow (cfs):	0 cfs	0 cfs
Sediment marker (install or replace)	In place	In place
Identification sign (install or replace)	In place	In place
EROSIONAL:		
Rills and/or gullies on downstream face.	No	No
Rills and/or gullies on upstream face.	No	No
Inadequate vegetation.	No	No
Outlet channel erosion.	No	No
Burrows.	No	No
Erosion of toe.	No	No
Water impounded against downstream toe.	No	No
Other.	—	—
STRUCTURAL:		
Differential settling.	No	No
Cracks, slides, or scarps.	No	No
Seepage (specify location, color, value).	No	No
Defective spillways.	No	No
Other.	—	—
APPURTENANT STRUCTURES:		
Defective spillways.	No	No
Dewatering device clogged.	NA	NA
Cracking or crushing of pipes.	NA	NA
Other.	—	—
COMMENTS:		



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Graham Roberts

SIGNATURE: Alh Rh

DRAINAGE: **JEFFWAY**

DATE OF INSPECTION: 6-10-20

POND IDENTIFICATION	Jeffway #1
Approximate water level:	0%
Sediment level (% total storage):	0%
Outflow (cfs):	0
Sediment marker (install or replace)	In place
Identification sign (install or replace)	In place
EROSIONAL:	
Rills and/or gullies on downstream face.	No
Rills and/or gullies on upstream face.	No
Inadequate vegetation.	No
Outlet channel erosion.	No
Burrows.	No
Erosion of toe.	No
Water impounded against downstream toe.	No
Other.	-
STRUCTURAL:	
Differential settling.	No
Cracks, slides, or scarps.	No
Seepage (specify location, color, value).	No
Defective spillways.	No
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	No
Dewatering device clogged.	NA
Cracking or crushing of pipes.	NA
Other.	-
COMMENTS:	



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR:

Tonia Perkins

SIGNATURE:

Tonia Perkins

DRAINAGE: IMPOUNDMENT H

DATE OF INSPECTION: *6/1/2020*

POND IDENTIFICATION	Impoundment H		
Approximate water level:	<i>15' 1/4</i>		
Sediment level (% total storage):	<i>5%</i>		
Outflow (cfs):	<i>0</i>		
Sediment marker (install or replace)	<i>In Place</i>		
Identification sign (install or replace)	<i>In Place</i>		
EROSIONAL:			
Rills and/or gullies on downstream face.	<i>NO</i>		
Rills and/or gullies on upstream face.	<i>NO</i>		
Inadequate vegetation.	<i>NO</i>		
Outlet channel erosion.	<i>NO</i>		
Burrows.	<i>NO</i>		
Erosion of toe.	<i>NO</i>		
Water impounded against downstream toe.	<i>NO</i>		
Other.	<i>-</i>		
STRUCTURAL:			
Differential settling.	<i>NO</i>		
Cracks, slides, or scarps.	<i>NO</i>		
Seepage (specify location, color, value).	<i>NO</i>		
Defective spillways.	<i>NO</i>		
Other.	<i>-</i>		
APPURTENANT STRUCTURES:			
Defective spillways.	<i>NO</i>		
Dewatering device clogged.	<i>NO</i>		
Cracking or crushing of pipes.	<i>NO</i>		
Other.	<i>-</i>		
COMMENTS:			



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia PerkinsSIGNATURE: Donie Perkins

DRAINAGE: INDUSTRIAL WASTE POND

DATE OF INSPECTION: 6/1/2020

POND IDENTIFICATION	Industrial Waste Pond #1
Approximate water level:	80'
Sediment level (% total storage):	5%
Outflow (cfs):	0
Sediment marker (install or replace)	N/A
Identification sign (install or replace)	In Place
EROSIONAL:	
Rills and/or gullies on downstream face.	no
Rills and/or gullies on upstream face.	no
Inadequate vegetation.	no
Outlet channel erosion.	no
Burrows.	no
Erosion of toe.	no
Water impounded against downstream toe.	no
Other.	-
STRUCTURAL:	
Differential settling.	no
Cracks, slides, or scarps.	no
Seepage (specify location, color, value).	no
Defective spillways.	no
Other.	-
APPURTENANT STRUCTURES:	
Defective spillways.	N/A
Dewatering device clogged.	N/A
Cracking or crushing of pipes.	N/A
Other.	-
COMMENTS:	

