

Notes:

9. Mining continued in the dry creek channel that was disturbed in years past (brown).

10. We continued to place backfill material along the south and west sides of the mined area west of West Bijou Creek (tan). Approximately 315 feet of the graded slopes along the east side of West Bijou Creek were partially destroyed in the high water event in 2014 (orange). The remaining 350 feet of sloping survived from previous years reclamation (green) and no other reclamation is required at this time. Approximately 0.24 acres was partially backfilled last year (yellow) with imported inert materials.

15. As noted in the Mining and Reclamation Plans there is no topsoil to salvage from the mining area.

19. The bond was evaluated by the Division in May 2019 and found to be adequate to complete reclamation.

22. Please refer to the 2020 Annual Report Map for location of the areas of disturbance in the mine.