



Morrison Quarry (M-1973-021) Stormwater

1 message

Lockman, Drew <alockman@geiconsultants.com>

Tue, Sep 15, 2020 at 9:51 AM

To: "Scott - DNR, Eric" <eric.scott@state.co.us>, "Cunningham - DNR, Michael" <michaela.cunningham@state.co.us>

Cc: Jeremy DEUTO <jeremy.deuto@lafargeholcim.com>

Good morning Eric and Michael.

Aggregate Industries removed the storm water that was stored and observed during the July 10, 2020 inspection, and provided the attached photos of the dewatered basin. Please let me know if these photos are sufficient documentation of the corrective action or if additional information is necessary.

Also, in follow-up conversations with Aggregate Industries they conveyed that the mine is adding an outfall at this location to the SWMP, which would enable the mine to pump directly from this basin into the appropriate watershed.

ANDREW LOCKMAN, P.G.
Geological Engineer

GEI50

303.264.1096 cell: 303.929.7012

4601 DTC Boulevard, Suite 900, Denver, CO 80237



2 attachments



78440702-B1AC-47DE-A0E0-BBE96E105020.jpeg
2856K

1BC97FF9-87FB-4DAD-AE15-2591963F81EE.jpeg
2838K

