## POND EXAMINATION FORM, 3rd QUARTER 2020

Mine: New Horizon North Mine Owner's Rep.: Frank Ferris, Mine Manager

Pond Name: Pond 001 Pond Type: Partly Incised NPDES Permit & Outfall #s: CO-850062 CDRM & S #: C-2010-089

Date Examined: 17-September-2020 Date Last Examined: 8-April-2020 Location Description: 2.4 miles NW of Nucla Legal Location: Sec 25 of T47N R16W

Inspector's Name: Frank Ferris

## Circle or Write appropriate Response

1.	Seepage (specify location, color, and approx. volume)			<b>1</b>	N/A
2.	Cracks or scarps on crest or slopes			<b>I</b>	N/A
3.	Sloughing or bulging on slopes		Yes	X	N/A
4.	Major erosion problems		Yes	K	N/A
5.	Surface movements in valley bottom or on hillside		Yes	NX.	N/A
6.	Water impounded against toe		Yes	N	N/A
7.	Clogging				
	a)	Spillway channels and pipes	Yes	X	N/A
	b)	Decant system	Yes	X	N/A
	c)	Diversion Ditches	Yes	N	N/A
8.	Cracking	g or crushing of pipes			
	a)	Spillway pipes	Yes	K	N/A
	b)	Decant system	Yes	K	N/A
9.	Trash racks clear and in place		<b>V</b> S	No	N/A
10.	Monitoring instrumentation		V	No	N/A

Comments: Pond bottom is dry.

## POND EXAMINATION FORM, 3rd QUARTER 2020

Mine: New Horizon North Mine Owner's Rep.: Frank Ferris, Mine Manager

Pond Name: Pond 002 Pond Type: Embankment

NPDES Permit & Outfall #s: CO-850062 CDRM & S #: C-2010-089

Date Examined: 17-September-2020 Date Last Examined: 8-April-2020

Location Description: 2.6 miles NW of Nucla Legal Location: Sec 25 of T47N R16W

Inspector's Name: Frank Ferris

## Circle or Write appropriate Response

l.	Seepa	Seepage (specify location, color, and approx. volume)			N/A
2.	Cracks or scarps on crest or slopes			X	N/A
3.	Sloughing or bulging on slopes				N/A
1.	Major erosion problems			X	N/A
5.	Surface movements in valley bottom or on hillside			X	N/A
5.	Water impounded against toe		Yes	X	N/A
7.	Clogg	ing			
	a)	Spillway channels and pipes	Yes	X	N/A
	b)	Decant system	Yes	X	N/A
	c)	Diversion Ditches	Yes	r 🔀	N/A
3.	Crack	ing or crushing of pipes			
	a)	Spillway pipes	Yes	X	N/A
	b)	Decant system	Yes		N/A
€.	Trash	racks clear and in place	Y	No	N/A
10.	Monitoring instrumentation		Y\$	No	N/A

Comments: Pond bottom is dry