

Attachment 1: Photos



Photo 1: Stormwater controls are adequate, very little erosion from side slope



Photo 2: Main site area



Photo 3: Hill side area



Photo 4: Some noxious weeds present, mitigated (sprayed) after site visit



Photo 5: Main gate signage, also found along mine perimeter