



**PERMIT INFORMATION**

<b>Permit Number:</b> C-1982-056 <b>Mine Name:</b> Foidel Creek Mine <b>Operator:</b> Twentymile Coal, LLC <b>Operator Address:</b> Ms Miranda Kawcak 29515 Routt County Road No. 27 Oak Creek, CO 80467	<b>County:</b> Routt <b>Operation Type:</b> Underground <b>Permit Status:</b> Active <b>Ownership:</b> Private
	<b>Operator Representative Present:</b>  Kevin Copeland
<b>Operator Representative Signature:</b> (Field Issuance Only)  	

**INSPECTION INFORMATION**

<b>Inspection Start Date:</b> November 10, 2020 <b>Inspection Start Time:</b> 10:00 <b>Inspection End Date:</b> November 10, 2020 <b>Inspection End Time:</b> 12:00		<b>Inspection Type:</b> Coal Partial Inspection <b>Inspection Reason:</b> Normal I&E Program <b>Weather:</b> Snowing	
<b>Joint Inspection Agency:</b>  None		<b>Joint Inspection Contacts:</b>  	
<b>Post Inspection Agency:</b>  None		<b>Post Inspection Contacts:</b>  	
<b>Inspector(s):</b>  Tabetha Lynch	<b>Inspector's Signature:</b> 		<b>Signature Date:</b>  11/13/20

**Inspection Topic Summary**

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

N - Air Resource Protection	Y - Roads
N - Availability of Records	N - Reclamation Success
N - Backfill & Grading	N - Revegetation
N - Excess Spoil and Dev. Waste	N - Subsidence
N - Explosives	R - Slides and Other Damage
N - Fish & Wildlife	N - Support Facilities On-site
R - Hydrologic Balance	Y - Signs and Markers
R - Gen. Compliance With Mine Plan	N - Support Facilities Not On-site
N - Other	N - Special Categories Of Mining
N - Processing Waste	Y - Topsoil

**COMMENTS**

This was coal partial inspection conducted at the Foidel Creek Mine by Tabetha Lynch with DRMS. Miranda Kawcak was present during the inspection. This inspection focused no following up on maintenance items from the complete inspection conducted in October.

**HYDROLOGIC BALANCE - Rule 4.05**

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

Leaking pipe a the fish creek borehole is still in the process of being repaired. Per the operator a part has been ordered to seal the leak.

The oil boom at pond B has not yet been placed to prevent the oil sheen from getting into the second cell of the pond.

**GENERAL MINE PLAN COMPLIANCE:**

Ditches appear to have been cleaned but were covered in snow during the inspection.

**SLIDES and DAMAGE - Rule 4.12:**

Work has not yet begun on the overland conveyor slide area near the train loadout.

Number of Partial Inspection this Fiscal Year: 4

Number of Complete Inspections this Fiscal Year: 2

**DOCUMENTS RECEIVED**

**OTHER (SPECIFY)**

**ENFORCEMENT ACTIONS/COMPLIANCE**

No enforcement actions were initiated as a result of this inspection, nor are any pending.

**PHOTOGRAPHS**



Cleared ditch



Location of leak at pump house

Number of Partial Inspection this Fiscal Year: 4

Number of Complete Inspections this Fiscal Year: 2