

## QUARTERLY POND INSPECTION REPORT

Operator:	McClane Canyon Mining LLC	Quarter:	Second 2020
Mine:	McClane Canyon Mine C-1980-004	Inspection Date:	29-Jun-20

### Pond Identification

Location

Sediment				
Pond				

### Status During Inspection:

Approximate Water Level

Sediment (% total storage)

Outflow (cfs)

5452				
100%				
0				

### Features

Problem

Yes/No

#### Erosional

Rills & Gulleys

Inadequate Vegetation

Outlet Channel Erosion

Burrows

Other

No				
No				
No				
No				
No				

#### Structural

Differential Settling

Cracks or Slides

Seepage

Other

No				
No				
No				
No				

#### Appurtenant Structures

Defective Spillways

Dewatering Devices Clogged

Faulty Gates, Etc.

Other

No				
No				
No				
No				


#### Additional Comments

Invert of primary spillway is at elevation 5457.00.  
Invert of emergency spillway is at elevation 5462.00.  
Pond bottom about 7' below primary spillway

Maintenance Required:

None

Name of Inspector: Jim Stover

  
 J. E. Stover  
 Colorado P. E. 19230 Date