

MINERALS PROGRAM INSPECTION REPORT PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:		MINE/PROSPECTING ID#:	MINERAL:	COUNTY:	
Hinds Pit #35		M-2003-070	Sand and gravel	Baca	
INSPECTION TYPE:		INSPECTOR(S):	INSP. DATE:	INSP. TIME:	
Monitoring		Daniel Cunningham	November 2, 2020	15:30	
OPERATOR:		OPERATOR REPRESENTATIVE:	TYPE OF OPERATION:		
Baca County		Shiloh Freed	112c - Construction Regular Operation		
REASON FOR INSPECTION:		BOND CALCULATION TYPE:	BOND AMOUNT:		
Normal I&E Program		None	\$0.00		
DATE OF COMPLAINT:		POST INSP. CONTACTS:	JOINT INSP. AGENCY:		
NA		None	None		
WEATHER:	INSPECTOR'S SIGNATURE:		SIGNATURE DATE:		
Clear	Danith Culputer		December 4, 2020		

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS <u>N</u>	(FN) FINANCIAL WARRANTY <u>N</u>	(RD) ROADS <u>Y</u>
(HB) HYDROLOGIC BALANCE <u>Y</u>	(BG) BACKFILL & GRADING <u>Y</u>	(EX) EXPLOSIVES <u>N</u>
(PW) PROCESSING WASTE/TAILING <u>N</u>	(SF) PROCESSING FACILITIES N	(TS) TOPSOIL <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE N	(RV) REVEGETATION <u>N</u>
(SM) SIGNS AND MARKERS <u>Y</u>	(SP) STORM WATER MGT PLAN <u>N</u>	(RS) RECL PLAN/COMP <u>N</u>
(ES) OVERBURDEN/DEV. WASTE <u>Y</u>	(SC) EROSION/SEDIMENTATION <u>N</u>	(ST) STIPULATIONS <u>N</u>
(AT) ACID OR TOXIC MATERIALS <u>N</u>	(OD) OFF-SITE DAMAGE <u>N</u>	

 $\mathbf{Y} = \mathbf{Inspected} \ / \ \mathbf{N} = \mathbf{Not} \ \mathbf{inspected} \ / \ \mathbf{NA} = \mathbf{Not} \ \mathbf{applicable} \ \mathbf{to} \ \mathbf{this} \ \mathbf{operation} \ / \ \mathbf{PB} = \mathbf{Problem} \ \mathbf{cited} \ / \ \mathbf{PV} = \mathbf{Possible} \ \mathbf{violation} \ \mathbf{cited} \ \mathbf{V} = \mathbf{Not} \ \mathbf{NA} = \mathbf{Not} \ \mathbf{No} = \mathbf{Not} \ \mathbf{No} = \mathbf{Not} \ \mathbf{No} = \mathbf{Not} \ \mathbf{No} = \mathbf{N$

OBSERVATIONS

This was a routine monitoring inspection conducted at the Hinds Pit #35 by DRMS representative DJ Cunningham. A representative of Baca County was present during the inspection representing the Operator. This site is an active, 20 acre, 112c permit, where approximately 15 acres has been disturbed to date. The site was not active at the time of the inspection.

The site identification sign was posted at the mine entrance and the boundary was marked. Several large stockpiles were seen throughout the site. Topsoil was being stored around the perimeter of the disturbed area. Slopes were graded at a 3H:1V or greater.

The previously noted standing water in the pit floor is no longer present.

No major issues were noted during the inspection.

PERMIT #: M-2003-070 INSPECTOR'S INITIALS: DC1 INSPECTION DATE: November 2, 2020

PHOTOGRAPHS



Stock Material



Topsoil

Inspection Contact Address

Baca County 121 W. 1st. Campo, CO 81090

Enclosure

CC: