




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: The Broyles Pit	MINE/PROSPECTING ID#: M-2004-028	MINERAL: Gravel	COUNTY: Las Animas
INSPECTION TYPE: Monitoring	INSPECTOR(S): Daniel Cunningham	INSP. DATE: November 3, 2020	INSP. TIME: 15:00
OPERATOR: Michele M and Frederick V Eichler IV	OPERATOR REPRESENTATIVE: Michele Eichler	TYPE OF OPERATION: 112c - Construction Regular Operation	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: Complete Bond	BOND AMOUNT: \$12,023.61	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
WEATHER: Clear	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: December 4, 2020	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>N</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>N</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>Y</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>Y</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>N</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This was a routine monitoring inspection conducted at The Broyles Pit by DRMS representative DJ Cunningham. A Michele Eichler was present during the inspection representing the Operator. This site is an active, 12.96 acre, 112c permit, where approximately 12 acres has been disturbed to date. The site was not active at the time of the inspection.

The site is divided into two sections, an eastern side and a western side. These two sections are connected by a haul road.

The site identification sign was posted at the mine entrance and the boundary was marked. A small stockpile of material was located on the western side of the permitted area. The eastern side has been graded at a 3H:1V slope. The seeding has not yet taken hold and it is recommended that the Operator reseed the area.

No major issues were noted during the inspection.

The Division currently holds a financial warranty in the amount of \$12,023.00. Based upon observations made during this inspection, the Division finds this amount adequate to conduct reclamation.

PHOTOGRAPHS



Mine Entrance



Eastern Side



Stock Material



Western Side

Inspection Contact Address

Michele Eichler
Michele M and Frederick V Eichler IV
22250 CR 44
Aguilar, CO 81020

Enclosure

CC: