




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Riverside Parkway	MINE/PROSPECTING ID#: M-2020-038	MINERAL: Gravel	COUNTY: Mesa
INSPECTION TYPE: Surety Release Inspection	INSPECTOR(S): Amy Yeldell	INSP. DATE: December 15, 2020	INSP. TIME: 12:30
OPERATOR: City of Grand Junction	OPERATOR REPRESENTATIVE: Bailie Tomlinson	TYPE OF OPERATION: 110c - Construction Limited Impact	
REASON FOR INSPECTION: Surety Related	BOND CALCULATION TYPE: None	BOND AMOUNT: No Bond Held	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: DRMS	JOINT INSP. AGENCY: None	
WEATHER: Clear	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: December 29, 2020	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>NA</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>NA</u>
(PW) PROCESSING WASTE/TAILING----- <u>NA</u>	(SF) PROCESSING FACILITIES----- <u>NA</u>	(TS) TOPSOIL----- <u>NA</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>Y</u>	(RV) REVEGETATION---- <u>Y</u>
(SM) SIGNS AND MARKERS----- <u>N</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>Y</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>Y</u>	(ST) STIPULATIONS----- <u>Y</u>
(AT) ACID OR TOXIC MATERIALS----- <u>NA</u>	(OD) OFF-SITE DAMAGE----- <u>NA</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted as part of the Colorado Division of Reclamation, Mining and Safety's (Division) normal monitoring program. Riverside Parkway is a Construction Materials Limited Impact 110 site which includes 9.05 acres that is in final reclamation. This site was previously permitted as a 111 permit (M-2007-005). The site has since been re-permitted with a different post-mining land use (industrial/commercial) and the 111 permit has been terminated.

The site is located within city limits of Grand Junction, Colorado. Bailie Tomlinson with River City Consultants represented the Operator and accompanied Amy Yeldell of the Division on the inspection.

The necessary improvements to the site to meet the final reclamation configuration have been completed. Stormwater features such as berms, ditches and sediment traps have all been properly installed. Cedar fencing has been placed as shown in the reclamation map. Roadways have been stabilized by the use of asphalt and gravel. Select areas have also been hydro seeded for additional slope stabilization.

Overall the site conforms to the approved reclamation plan. This inspection will serve as the surety release inspection. On December 21, 2020 the Division received SL-1. The Division is in the process of reviewing this request. A decision letter will be sent under a separate cover.

No problems or violations were noted during this inspection. No bond is required for this site.

Responses to this inspection report should be directed to: Amy Yeldell at the Division of Reclamation, Mining and Safety, 1313 Sherman St., Room 215, Denver, CO 80203. Direct contact can be made by phone at 303-866-3567 Ext 8183 or via email at amy.yeldell@state.co.us

Inspection Contact Address

Trent Prall
City of Grand Junction
250 N 5th St
Grand Junction, CO 81501

Enclosure

EC:
Travis Marshall, Senior EPS, Grand Junction DRMS
Bailie Tomlinson, River City Consultants

PHOTOGRAPHS



