

QUARTERLY POND INSPECTION REPORT

Operator:	ARC McClane Canyon LLC	Quarter:	Fourth 2020
Mine:	McClane Canyon Mine C-1980-004	Inspection Date:	14-Nov-20

Pond Identification

Location

Sediment				
Pond				

Status During Inspection:

Approximate Water Level

Sediment (% total storage)

Outflow (cfs)

Dry				
100%				
0				

Features

Problem

Yes/No

Erosional

Rills & Gulleys

Inadequate Vegetation

Outlet Channel Erosion

Burrows

Other

No

No

No

No

No

Structural

Differential Settling

Cracks or Slides

Seepage

Other

No

No

No

No

Appurtenant Structures

Defective Spillways

Dewatering Devices Clogged

Faulty Gates, Etc.

Other

No

No

No

No



Additional Comments

Invert of primary spillway is at elevation 5457.00.


Invert of emergency spillway is at elevation 5462.00.

Pond bottom about 7' below primary spillway

Maintenance Required:

None

Name of Inspector: Jim Stover



J. E. Stover
Colorado P. E. 19230 Date